

## **Transport Department Notice**

### **Temporary Traffic and Transport Arrangements on Fanling Highway**

Notice is hereby given that to facilitate road works on Fanling Highway, the following temporary traffic and transport arrangements will be implemented from 1 a.m. to 6 a.m. daily on 26 March, 9, 10, 16 and 17 April 2024:

#### **(1) ROAD CLOSURE**

The following road sections will be temporarily closed to all vehicular traffic:

- (a) The slip road leading from Hong Lok Yuen Road to Fanling Highway northbound;
- (b) The slip road leading from Tai Wo Service Road West southbound to Fanling Highway northbound;
- (c) The slip road leading from Heung Yuen Wai Highway to Fanling Highway northbound; and
- (d) The section of Fanling Highway northbound from its junction with Tolo Highway northbound to So Kwun Po Road roundabout.

#### **(2) TRAFFIC DIVERSION**

- (a) Vehicles on Lam Kam Road Interchange or Hong Lok Yuen Road westbound heading for Fanling will be diverted via Tai Wo Service Road West northbound, Wo Hing Road southbound, Wo Hing Road westbound and Pak Wo Road;
- (b) Vehicles on Lam Kam Road Interchange or Hong Lok Yuen Road westbound heading for Sheung Shui or Yuen Long will be diverted via Tai Wo Service Road West northbound, Wo Hing Road southbound, Wah Ming Road roundabout, Wah Ming Road northbound, Pak Wo Road westbound, So Kwun Po Road northbound and So Kwun Po Road roundabout;
- (c) Vehicles on Lam Kam Road Interchange or Hong Lok Yuen Road westbound heading for Heung Yuen Wai will be diverted via Tai Wo Service Road West northbound, Wo Hing Road southbound, Wo Hing Road westbound, Pak Wo Road northbound, slip road, Fanling Highway southbound and Heung Yuen Wai Highway;
- (d) Vehicles on Tai Wo Service Road West southbound, Tolo Highway northbound or Heung Yuen Wai Highway southbound heading for Fanling will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road southbound, Wo Hing Road westbound and Pak Wo Road;
- (e) Vehicles on Tai Wo Service Road West southbound, Tolo Highway northbound or Heung Yuen Wai Highway southbound heading for Sheung Shui or Yuen Long will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road southbound, Wah Ming Road roundabout, Wah Ming Road northbound, Pak Wo Road westbound, So Kwun Po Road northbound and So Kwun Po Road roundabout; and
- (f) Vehicles on Tai Wo Service Road West southbound or Tolo Highway northbound heading for Heung Yuen Wai will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road southbound, Wo Hing Road westbound, Pak Wo Road northbound, slip road, Fanling Highway southbound and Heung Yuen Wai Highway.

### **(3) PUBLIC TRANSPORT SERVICE ARRANGEMENTS**

#### **(A) Franchised Bus Service**

- (a) KMB Route Nos. 270A (Sheung Shui bound), 270S (Luen Wo Hui bound) and 278X (Sheung Shui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road southbound, Wah Ming Road roundabout, Wah Ming Road northbound before resuming their normal routing;
- (b) KMB Route No. 277X (Luen Wo Hui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road southbound, Wah Ming Road roundabout before resuming its normal routing. The en-route stop at Wo Hing Tsuen will be suspended; and
- (c) LWB Route No. N42A (Luen Wo Hui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road southbound, Wah Ming Road roundabout, Wah Ming Road northbound, Pak Wo Road westbound, So Kwun Po Road northbound, So Kwun Po Road roundabout before resuming its normal routing.

#### **(B) Green Minibus Service**

- (a) GMB Route No. 501S (Sheung Shui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road southbound, Wah Ming Road roundabout before resuming its normal routing; and
- (b) GMB route no. 616S (Lok Ma Chau bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road southbound, Wo Hing Road westbound, Pak Wo Road northbound, Jockey Club Road northbound, So Kwun Po Road westbound, So Kwun Po Road roundabout, Fanling Highway northbound before resuming its normal routing.

Appropriate traffic signs will be erected on site to guide motorists. Motorists are advised to follow the instructions on site and drive in utmost care. The public transport operators will display notices to advise passengers of the above temporary arrangements.

LEE Chung-yan, Angela *Commissioner for Transport*