

Recall Detail	
Ref No	10000277
Manufacturer	Land Rover
Vehicle Class	N1 – Light Goods Vehicle
Model/Type	Defender
Dealer (phone no. / e-mail)	British Motors Limited - (Tel: 2821 7100 or 2820 5150 / service@britishmotors.com.hk)
Subject	Inspection of Parking Brake
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The shoes of the parking brake could be contaminated with oil which has leaked from the rear of the transfer box. Where oil from the transfer box has impregnated the park brake shoes, the park brake may not hold the vehicle when the park brake lever is applied and the vehicle may instantaneously roll.
Remedial Action	To inspect the park brake shoes and replace it when necessary.
Build Dates	2007 to 2011
Launch Date	26 July 2011
Tentative Date of Recall Completion	31 December 2016

1	SALLDHFS77A743581
2	SALLDHMS77A744496
3	SALLDHMS77A745893
4	SALLDHMS77A752221
5	SALLDHMS77A752408
6	SALLDVAS77A743450
7	SALLDVAS77A744644
8	SALLDVAS77A747504
9	SALLDVBS77A752294