

車輛安全召回資訊

Vehicle Safety Recall Information

10000288-2

製造商 Make: 本田 Honda

型 號 Model: Accord 2.3 / CG5

項 目 Subject: 司機位安全氣囊改良運動

Driver's Airbag Inflator Replacement

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1	JHMC	G56601C200003
2	JHMC	G56601C200004
3	JHMC	G56601C200005
4	JHMC	G56601C200006
5	JHMC	G56601C200007
6	JHMC	G56601C200008
7	JHMC	G56601C200009
8	JHMC	G56601C200010
9	JHMC	G56601C200011
10	JHMC	G56601C200012
11	JHMC	G56601C200013
12	JHMC	G56601C200014
13	JHMC	G56601C200015
14	JHMC	G56601C200016
15	JHMC	G56601C200017
16	JHMC	G56601C200018
17	JHMC	G56601C200019
18	JHMC	G56601C200020
19	JHMC	G56601C200032
20	JHMC	G56601C200033
21	JHMC	G56601C200034
22	JHMC	G56601C200035
23	JHMC	G56601C200036
24	JHMC	G56601C200037
25	JHMC	G56601C200038
26	JHMC	G56601C200039
27	JHMC	G56601C200040
28	JHMC	G56601C200041
29	JHMC	G56601C200042
30	JHMC	G56601C200043
31	JHMC	G56601C200044
32	JHMC	G56601C200045
33	JHMC	G56601C200046
34	JHMC	G56601C200047

35	JHMC	G56601C200048
36	JHMC	G56601C200049
37	JHMC	G56601C200050
38	JHMC	G56601C200057
39	JHMC	G56601C200058
40	JHMC	G56601C200059
41	JHMC	G56601C200060
42	JHMC	G56601C200061
43	JHMC	G56601C200062
44	JHMC	G56601C200063
45	JHMC	G56601C200064
46	JHMC	G56601C200065
47	JHMC	G56601C200066
48	JHMC	G56601C200067
49	JHMC	G56601C200068
50	JHMC	G56601C200069
51	JHMC	G56601C200070
52	JHMC	G56601C200071
53	JHMC	G56601C200072
54	JHMC	G56601C200073
55	JHMC	G56601C200074
56	JHMC	G56601C200075
57	JHMC	G56601C200076
58	JHMC	G56601C200077
59	JHMC	G56601C200078
60	JHMC	G56601C200079
61	JHMC	G56601C200080
62	JHMC	G56601C200081
63	JHMC	G56601C200082
64	JHMC	G56601C200083
65	JHMC	G56601C200084
66	JHMC	G56601C200085
67	JHMC	G56601C200086
68	JHMC	G56601C200087

車輛安全召回資訊

Vehicle Safety Recall Information

10000288-2

製造商 Make: 本田 Honda

型 號 Model: Accord 2.3 / CG5

項 目 Subject: 司機位安全氣囊改良運動

Driver's Airbag Inflator Replacement

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

69	JHMC	G56601C200088
70	JHMC	G56601C200089
71	JHMC	G56601C200090
72	JHMC	G56601C200091
73	JHMC	G56601C200092
74	JHMC	G56601C200093
75	JHMC	G56601C200094
76	JHMC	G56601C200095
77	JHMC	G56601C200096
78	JHMC	G56601C200097
79	JHMC	G56601C200098
80	JHMC	G56601C200099
81	JHMC	G56601C200100
82	JHMC	G56601C200101
83	JHMC	G56601C200102
84	JHMC	G56601C200103
85	JHMC	G56601C200104
86	JHMC	G56601C200105
87	JHMC	G56601C200106
88	JHMC	G56601C200107
89	JHMC	G56601C200108
90	JHMC	G56601C200109
91	JHMC	G56601C200110
92	JHMC	G56601C200111
93	JHMC	G56601C200112
94	JHMC	G56601C200113
95	JHMC	G56601C200114
96	JHMC	G56601C200115
97	JHMC	G56601C200116
98	JHMC	G56601C200117
99	JHMC	G56601C200118
100	JHMC	G56601C200119
101	JHMC	G56601C200120
102	JHMC	G56601C200121
103	JHMC	G56601C200122

104	JHMC	G56601C200123
105	JHMC	G56601C200124
106	JHMC	G56601C200125
107	JHMC	G56601C200196
108	JHMC	G56601C200197
109	JHMC	G56601C200198
110	JHMC	G56601C200199
111	JHMC	G56601C200200
112	JHMC	G56601C200201
113	JHMC	G56601C200202
114	JHMC	G56601C200203
115	JHMC	G56601C200205
116	JHMC	G56601C200206
117	JHMC	G56601C200207
118	JHMC	G56601C200208
119	JHMC	G56601C200209
120	JHMC	G56601C200210
121	JHMC	G56601C200211
122	JHMC	G56601C200212
123	JHMC	G56601C200213
124	JHMC	G56601C200214
125	JHMC	G56601C200215
126	JHMC	G56601C200216
127	JHMC	G56601C200217
128	JHMC	G56601C200218
129	JHMC	G56601C200219
130	JHMC	G56601C200241
131	JHMC	G56601C200242
132	JHMC	G56601C200243
133	JHMC	G56601C200244
134	JHMC	G56601C200245
135	JHMC	G56601C200246
136	JHMC	G56601C200247
137	JHMC	G56601C200248
138	JHMC	G56601C200249

車輛安全召回資訊

Vehicle Safety Recall Information

10000288-2

製造商 Make: 本田 Honda

型 號 Model: Accord 2.3 / CG5

項 目 Subject: 司機位安全氣囊改良運動

Driver's Airbag Inflator Replacement

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

139	JHMC	G56601C200250
140	JHMC	G56601C200251
141	JHMC	G56601C200252
142	JHMC	G56601C200253
143	JHMC	G56601C200254
144	JHMC	G56601C200255
145	JHMC	G56601C200256
146	JHMC	G56601C200257
147	JHMC	G56601C200258
148	JHMC	G56601C200260
149	JHMC	G56601C200261
150	JHMC	G56601C200262
151	JHMC	G56601C200263
152	JHMC	G56601C200264
153	JHMC	G56601C200265
154	JHMC	G56601C200266
155	JHMC	G56601C200267
156	JHMC	G56601C200269
157	JHMC	G56601C200270
158	JHMC	G56601C200274
159	JHMC	G56601C200275
160	JHMC	G56601C200277
161	JHMC	G56601C200278
162	JHMC	G56601C200280
163	JHMC	G56601C200282
164	JHMC	G56601C200283
165	JHMC	G56601C200284
166	JHMC	G56601C200285
167	JHMC	G56601C200286
168	JHMC	G56601C200288
169	JHMC	G56601C200289
170	JHMC	G56601C200417
171	JHMC	G56601C200418
172	JHMC	G56601C200419
173	JHMC	G56601C200420

174	JHMC	G56601C200421
175	JHMC	G56601C200422
176	JHMC	G56601C200423
177	JHMC	G56601C200424
178	JHMC	G56601C200425
179	JHMC	G56601C200426
180	JHMC	G56601C200470
181	JHMC	G56601C200471
182	JHMC	G56601C200472
183	JHMC	G56601C200473
184	JHMC	G56601C200474
185	JHMC	G56601C200475
186	JHMC	G56601C200476
187	JHMC	G56601C200477
188	JHMC	G56601C200478
189	JHMC	G56601C200479
190	JHMC	G56601C200495
191	JHMC	G56601C200496
192	JHMC	G56601C200497
193	JHMC	G56601C200498
194	JHMC	G56601C200499
195	JHMC	G56601C200500
196	JHMC	G56601C200501
197	JHMC	G56601C200502
198	JHMC	G56601C200513
199	JHMC	G56601C200514
200	JHMC	G56601C200515
201	JHMC	G56601C200516
202	JHMC	G56601C200517
203	JHMC	G56601C200518
204	JHMC	G56601C200519
205	JHMC	G56601C200520
206	JHMC	G56601C200521
207	JHMC	G56601C200522
208	JHMC	G56601C200523

車輛安全召回資訊

Vehicle Safety Recall Information

10000288-2

製造商 Make: 本田 Honda

型 號 Model: Accord 2.3 / CG5

項 目 Subject: 司機位安全氣囊改良運動

Driver's Airbag Inflator Replacement

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

209	JHMC	G56601C200524
210	JHMC	G56601C200525
211	JHMC	G56601C200526
212	JHMC	G56601C200527
213	JHMC	G56601C200528
214	JHMC	G56601C200529
215	JHMC	G56601C200530
216	JHMC	G56601C200531
217	JHMC	G56601C200532
218	JHMC	G56601C200533
219	JHMC	G56601C200534
220	JHMC	G56601C200535
221	JHMC	G56601C200536
222	JHMC	G56601C200537
223	JHMC	G56601C200538
224	JHMC	G56601C200539
225	JHMC	G56601C200540
226	JHMC	G56601C200541
227	JHMC	G56601C200542
228	JHMC	G56601C200549
229	JHMC	G56601C200550
230	JHMC	G56601C200551
231	JHMC	G56601C200552
232	JHMC	G56601C200560
233	JHMC	G56601C200561
234	JHMC	G56601C200562
235	JHMC	G56601C200563
236	JHMC	G56601C200564

237	JHMC	G56601C200565
238	JHMC	G56601C200567
239	JHMC	G56601C200568
240	JHMC	G56601C200570
241	JHMC	G56601C200571
242	JHMC	G56601C200572
243	JHMC	G56601C200573
244	JHMC	G56601C200574
245	JHMC	G56601C200575
246	JHMC	G56601C200581
247	JHMC	G56601C200582
248	JHMC	G56601C200583
249	JHMC	G56601C200584
250	JHMC	G56601C200586
251	JHMC	G56601C200587
252	JHMC	G56601C200588
253	JHMC	G56601C200589
254	JHMC	G56601C200590
255	JHMC	G56601C200591
256	JHMC	G56601C200592
257	JHMC	G56601C200595
258	JHMC	G56601C200623
259	JHMC	G56601C200630
260	JHMC	G56601C200631
261	JHMC	G56601C200632
262	JHMC	G56601C200633
263	JHMC	G56601C200634