

## Recall Detail

<b>Ref No</b>	<b>10000374</b>
<b>Manufacturer</b>	BMW
<b>Vehicle Class</b>	Passenger Car
<b>Model/Type</b>	X5, X6, 5 series, 6 series and 7 series E7x, F0x, and F1x
<b>Dealer (phone no)</b>	31882677
<b>Subject</b>	Replace additional coolant pump
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below: (Last Seven Numbers)
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Incorrect warning message "Engine Overheating" may appear in instrument, upgrade on related item is required.
<b>Remedial Action</b>	Replace additional coolant pump
<b>Build Dates</b>	16-11-2007 – 02-02-2011
<b>Launch Date</b>	28/10/2011
<b>Tentative Date of Recall Completion</b>	30/04/2012

1	<b>B590906</b>
2	<b>B590907</b>
3	<b>B590908</b>
4	<b>B998033</b>
5	<b>B998061</b>
6	<b>B998069</b>
7	<b>B998086</b>
8	<b>B998116</b>
9	<b>B998132</b>
10	<b>C216008</b>
11	<b>C216065</b>
12	<b>C216066</b>
13	<b>C216067</b>
14	<b>C216068</b>
15	<b>C216079</b>
16	<b>C216081</b>
17	<b>C216082</b>
18	<b>C216086</b>
19	<b>C216109</b>
20	<b>C216111</b>
21	<b>C216119</b>

22	<b>C216132</b>
23	<b>C216134</b>
24	<b>C216135</b>
25	<b>C216136</b>
26	<b>C216138</b>
27	<b>C216140</b>
28	<b>C216144</b>
29	<b>C216145</b>
30	<b>C216146</b>
31	<b>C216147</b>
32	<b>C216150</b>
33	<b>C216154</b>
34	<b>C216155</b>
35	<b>C216158</b>
36	<b>C216163</b>
37	<b>C216166</b>
38	<b>C216168</b>
39	<b>C216169</b>
40	<b>C216170</b>
41	<b>C216171</b>
42	<b>C216175</b>

43	<b>C216177</b>
44	<b>C216181</b>
45	<b>C216188</b>
46	<b>C216189</b>
47	<b>C216193</b>
48	<b>C216194</b>
49	<b>C216198</b>
50	<b>C216199</b>
51	<b>C216200</b>
52	<b>C216201</b>
53	<b>C216202</b>
54	<b>C216203</b>
55	<b>C216204</b>
56	<b>C216205</b>
57	<b>C216208</b>
58	<b>C216211</b>
59	<b>C216212</b>
60	<b>C216217</b>
61	<b>C216218</b>
62	<b>C216219</b>
63	<b>C216221</b>
64	<b>C216228</b>
65	<b>C216229</b>
66	<b>C216231</b>
67	<b>C216232</b>
68	<b>C216235</b>
69	<b>C216236</b>
70	<b>C216237</b>
71	<b>C216238</b>
72	<b>C216239</b>
73	<b>C216240</b>
74	<b>C216242</b>
75	<b>C216246</b>
76	<b>C216247</b>
77	<b>C216249</b>
78	<b>C216251</b>
79	<b>C216252</b>
80	<b>C216253</b>
81	<b>C216254</b>
82	<b>C216255</b>

83	<b>C272005</b>
84	<b>C272008</b>
85	<b>C272014</b>
86	<b>C272017</b>
87	<b>C272019</b>
88	<b>C272025</b>
89	<b>C272033</b>
90	<b>C272036</b>
91	<b>C272041</b>
92	<b>C272051</b>
93	<b>C272053</b>
94	<b>C272055</b>
95	<b>C272058</b>
96	<b>C272063</b>
97	<b>C272064</b>
98	<b>C272077</b>
99	<b>C272080</b>
100	<b>C272083</b>
101	<b>C272089</b>
102	<b>C272103</b>
103	<b>C272132</b>
104	<b>C272146</b>
105	<b>C272148</b>
106	<b>C272151</b>
107	<b>C272162</b>
108	<b>C272163</b>
109	<b>C272165</b>
110	<b>C272166</b>
111	<b>C272167</b>
112	<b>C272169</b>
113	<b>C272170</b>
114	<b>C272171</b>
115	<b>C272172</b>
116	<b>C272173</b>
117	<b>C272178</b>
118	<b>C272179</b>
119	<b>C272181</b>
120	<b>C272183</b>
121	<b>C272210</b>
122	<b>C272211</b>

123	<b>CK77186</b>
124	<b>CY55045</b>
125	<b>CY55101</b>
126	<b>CY55102</b>
127	<b>CY55103</b>
128	<b>CY55114</b>
129	<b>CY55124</b>
130	<b>CY55127</b>
131	<b>CY55131</b>
132	<b>CY55135</b>
133	<b>CY55136</b>
134	<b>CY55137</b>
135	<b>CY55139</b>
136	<b>CY55140</b>
137	<b>CY55141</b>
138	<b>CY55143</b>
139	<b>CY55146</b>
140	<b>CY55147</b>
141	<b>CY55148</b>
142	<b>CY55153</b>
143	<b>CY55154</b>
144	<b>CY55155</b>
145	<b>CY55156</b>
146	<b>CY55157</b>
147	<b>CY55158</b>
148	<b>CY55161</b>
149	<b>CY55163</b>
150	<b>CY55165</b>
151	<b>CY55167</b>
152	<b>CY55168</b>
153	<b>CY55169</b>
154	<b>CY55170</b>
155	<b>CY55171</b>
156	<b>CY55172</b>
157	<b>CY55173</b>
158	<b>CY55174</b>
159	<b>CY55175</b>
160	<b>CY55272</b>
161	<b>CY55276</b>
162	<b>CY55293</b>

163	<b>CY55302</b>
164	<b>CY55307</b>
165	<b>CY55310</b>
166	<b>CY55333</b>
167	<b>CY55337</b>
168	<b>CY55345</b>
169	<b>CY55371</b>
170	<b>CY55373</b>
171	<b>CY55390</b>
172	<b>CY55391</b>
173	<b>CY55395</b>
174	<b>CY55418</b>
175	<b>CY55422</b>
176	<b>CY55427</b>
177	<b>CY55456</b>
178	<b>CY55461</b>
179	<b>CY55462</b>
180	<b>CY55472</b>
181	<b>CY55478</b>
182	<b>CY55492</b>
183	<b>CY55494</b>
184	<b>CY55499</b>
185	<b>CY55511</b>
186	<b>CY55562</b>
187	<b>CY55569</b>
188	<b>CY55580</b>
189	<b>CY55588</b>
190	<b>CY55601</b>
191	<b>CY55602</b>
192	<b>CY55604</b>
193	<b>CY55608</b>
194	<b>CY55609</b>
195	<b>CY55619</b>
196	<b>CY55630</b>
197	<b>CY55631</b>
198	<b>CY55633</b>
199	<b>CY55635</b>
200	<b>CY55636</b>
201	<b>CY55644</b>
202	<b>CY55645</b>

203	<b>CY55649</b>
204	<b>CY55650</b>
205	<b>CY55666</b>
206	<b>CY55669</b>
207	<b>CY55674</b>
208	<b>CY55676</b>
209	<b>CY55688</b>
210	<b>CY55693</b>
211	<b>CY55694</b>
212	<b>CY55696</b>
213	<b>CY55697</b>
214	<b>CY55698</b>
215	<b>CY55701</b>
216	<b>CY55707</b>
217	<b>CY55710</b>
218	<b>CY55711</b>
219	<b>CY55714</b>
220	<b>CY55716</b>
221	<b>CY55717</b>
222	<b>CY55741</b>
223	<b>CY55743</b>
224	<b>CY55754</b>
225	<b>CY55757</b>
226	<b>CY55760</b>
227	<b>CY55769</b>
228	<b>CY55770</b>
229	<b>CY55771</b>
230	<b>CY55774</b>
231	<b>CY55776</b>
232	<b>CY55778</b>
233	<b>CY55779</b>
234	<b>CY55780</b>
235	<b>CY55781</b>
236	<b>CY55782</b>
237	<b>CY55783</b>
238	<b>CY55784</b>
239	<b>CY55789</b>
240	<b>CY55795</b>
241	<b>CY55796</b>
242	<b>CY55797</b>

243	<b>CY55800</b>
244	<b>CY55817</b>
245	<b>CY55819</b>
246	<b>CY55820</b>
247	<b>CY55825</b>
248	<b>CY55834</b>
249	<b>CY55841</b>
250	<b>CY55848</b>
251	<b>CY55853</b>
252	<b>CY55855</b>
253	<b>CY55858</b>
254	<b>CY55859</b>
255	<b>CY55861</b>
256	<b>CY55863</b>
257	<b>CY55864</b>
258	<b>CY55865</b>
259	<b>CY55896</b>
260	<b>CY55898</b>
261	<b>CY55899</b>
262	<b>CY55902</b>
263	<b>CY55904</b>
264	<b>CY55905</b>
265	<b>CY55906</b>
266	<b>CY55907</b>
267	<b>CY55910</b>
268	<b>CY55913</b>
269	<b>CY55915</b>
270	<b>CY55916</b>
271	<b>CY55917</b>
272	<b>CY55918</b>
273	<b>CY55925</b>
274	<b>CY55926</b>
275	<b>CY55928</b>
276	<b>CY55929</b>
277	<b>CY55930</b>
278	<b>CY55931</b>
279	<b>CY55932</b>
280	<b>CY55933</b>
281	<b>CY55934</b>
282	<b>CY55935</b>

283	<b>CY55938</b>
284	<b>CY55970</b>
285	<b>CY55972</b>
286	<b>CY55973</b>
287	<b>CY55974</b>
288	<b>CY55979</b>
289	<b>CY55989</b>
290	<b>CY55993</b>
291	<b>CY56000</b>
292	<b>CY56017</b>
293	<b>CY56019</b>
294	<b>CY56025</b>
295	<b>CY56026</b>
296	<b>CY56027</b>
297	<b>CY56029</b>
298	<b>CY56030</b>
299	<b>CY56031</b>
300	<b>CY56032</b>
301	<b>CY56034</b>
302	<b>LG99256</b>
303	<b>LG99262</b>
304	<b>LG99264</b>
305	<b>LG99266</b>
306	<b>LG99267</b>
307	<b>LG99268</b>
308	<b>LG99319</b>
309	<b>LG99327</b>
310	<b>LG99367</b>
311	<b>LG99368</b>
312	<b>LG99369</b>
313	<b>LH67013</b>
314	<b>LH67268</b>
315	<b>LH67269</b>
316	<b>LH67272</b>
317	<b>LH67393</b>
318	<b>LJ88512</b>
319	<b>LJ88769</b>
320	<b>LJ88770</b>
321	<b>LJ88771</b>
322	<b>LJ88777</b>

323	<b>LJ88779</b>
324	<b>LJ88783</b>
325	<b>LJ88784</b>
326	<b>LJ88786</b>
327	<b>LJ88797</b>
328	<b>LJ88812</b>
329	<b>LJ88822</b>
330	<b>LJ88880</b>
331	<b>LL67029</b>
332	<b>LL67035</b>
333	<b>LL67036</b>
334	<b>LL67099</b>
335	<b>LL67103</b>
336	<b>LL67143</b>
337	<b>LL67164</b>
338	<b>LL67165</b>
339	<b>LL67166</b>
340	<b>LL67167</b>
341	<b>LL67183</b>
342	<b>LL67187</b>
343	<b>LL67207</b>
344	<b>LL67210</b>
345	<b>LL67218</b>
346	<b>LL67219</b>
347	<b>LL67223</b>
348	<b>LL67244</b>
349	<b>LL67245</b>
350	<b>LL67258</b>
351	<b>LL67261</b>
352	<b>LL67291</b>
353	<b>LL67292</b>
354	<b>LL67328</b>
355	<b>LL79062</b>
356	<b>LL79092</b>
357	<b>LL79102</b>
358	<b>LL79104</b>
359	<b>LL79165</b>
360	<b>LL79235</b>
361	<b>LL79239</b>
362	<b>LL79243</b>

363	<b>LL79260</b>
364	<b>LL79289</b>
365	<b>LL79308</b>
366	<b>LL79341</b>
367	<b>LL79342</b>
368	<b>LL79350</b>
369	<b>LL79361</b>
370	<b>LL79381</b>
371	<b>LL79385</b>
372	<b>LL79394</b>