

| Recall Detail | |
|--|--|
| Ref No | 10000383 |
| Manufacturer | Mitsubishi Motors Corporation |
| Vehicle Class | Private car |
| Model/Type | Pajero (V65W, V73W & V75W) |
| Dealer (phone no) | Sime Darby Motor Services Limited (Tel: 3913 8800) |
| Subject | HBB accumulator rectification work |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | <p>In the accumulator of the hydraulic brake booster, since the operation in the manufacturing process is improper, the resin film (diaphragm) inside of the accumulator may get damaged. If use continues under this condition, the cracking in the diaphragm may occur and the amount of the nitrogen gas enclosed in the accumulator may decrease resulting in the following phenomenon.</p> <p>1) The brake assist may delay at rapid braking.</p> <p>2) The brake pedal effort may increase when the engine is started after the vehicle is kept stopping for a long time period.</p> |
| Remedial Action | Check and replace the accumulator if necessary |
| Build Dates | From 2000 to 2003 |
| Launch Date | 23/03/2012 |
| Tentative Date of Recall Completion | 22/03/2013 |

| | |
|----|-------------------|
| 1 | JMYLNV73W2J000510 |
| 2 | JMYLNV73W2J000516 |
| 3 | JMYLNV73W2J000519 |
| 4 | JMYLNV73W2J000530 |
| 5 | JMYLNV73W2J000571 |
| 6 | JMYLNV73W2J000573 |
| 7 | JMYLNV73W2J000592 |
| 8 | JMYLNV73W2J000627 |
| 9 | JMYLNV73W2J000628 |
| 10 | JMYLNV73W2J000633 |
| 11 | JMYLNV73W2J000635 |
| 12 | JMYLNV73W2J000640 |
| 13 | JMYLNV73W2J000666 |
| 14 | JMYLNV73W2J000667 |

| | |
|----|-------------------|
| 15 | JMYLNV73W2J000669 |
| 16 | JMYLNV73W2J000670 |
| 17 | JMYLNV73W2J000676 |
| 18 | JMYLNV73W3J000579 |
| 19 | JMYLNV73W3J000583 |
| 20 | JMYLNV73W4J000138 |
| 21 | JMYLNV73W4J000140 |
| 22 | JMYLNV73W4J000144 |
| 23 | JMYLNV73W4J000146 |
| 24 | JMYLNV73W4J000148 |
| 25 | JMYLNV73W4J000152 |
| 26 | JMYLRV73W2J000302 |
| 27 | JMYLRV73W2J000311 |
| 28 | JMYLRV73W2J000315 |

| | |
|----|-------------------|
| 29 | JMYLRV73W2J000320 |
| 30 | JMYLRV73W2J000335 |
| 31 | JMYLRV73W2J000340 |
| 32 | JMYLRV73W2J000370 |
| 33 | JMYLRV73W2J000403 |
| 34 | JMYLRV73W2J000404 |
| 35 | JMYLRV73W2J000406 |
| 36 | JMYLRV73W2J000464 |
| 37 | JMYLRV73W2J000471 |
| 38 | JMYLRV73W2J000474 |
| 39 | JMYLRV73W2J000475 |
| 40 | JMYLRV73W2J000477 |
| 41 | JMYLRV73W2J000483 |
| 42 | JMYLRV73W3J001392 |
| 43 | JMYLRV73W3J001851 |
| 44 | JMYLRV73W3J001885 |
| 45 | JMYLRV73W3J001891 |
| 46 | JMYLRV73W3J003557 |
| 47 | JMYLRV73W3J003578 |
| 48 | JMYLRV73W3J003726 |
| 49 | JMYLRV73W3J003787 |
| 50 | JMYLRV73W3J003998 |
| 51 | JMYLRV73W4J000162 |
| 52 | JMYLRV73W4J000163 |
| 53 | JMYLYV75W1J000102 |
| 54 | JMYLYV75W1J000114 |
| 55 | JMYLYV75W1J000116 |
| 56 | JMYLYV75W1J000117 |
| 57 | JMYLYV75W1J000118 |
| 58 | JMYLYV75W1J000119 |
| 59 | JMYLYV75W1J000124 |
| 60 | JMYLYV75W1J000125 |
| 61 | JMYLYV75W1J000129 |
| 62 | JMYLYV75W1J000130 |
| 63 | JMYLYV75W1J000131 |
| 64 | JMYLYV75W1J000132 |
| 65 | JMYLYV75W1J000137 |
| 66 | JMYLYV75W1J000138 |
| 67 | JMYLYV75W1J000142 |
| 68 | JMYLYV75W1J000143 |

| | |
|-----|-------------------|
| 69 | JMYLYV75W1J000170 |
| 70 | JMYLYV75W1J000174 |
| 71 | JMYLYV75W1J000178 |
| 72 | JMYLYV75W1J000183 |
| 73 | JMYLYV75W1J000195 |
| 74 | JMYLYV75W1J000198 |
| 75 | JMYLYV75W1J000230 |
| 76 | JMYLYV75W1J000231 |
| 77 | JMYLYV75W1J000236 |
| 78 | JMYLYV75W1J000237 |
| 79 | JMYLYV75W1J000238 |
| 80 | JMYLYV75W1J000240 |
| 81 | JMYLYV75W1J000241 |
| 82 | JMYLYV75W1J000251 |
| 83 | JMYLYV75W1J000279 |
| 84 | JMYLYV75W1J000386 |
| 85 | JMYLYV75W1J000397 |
| 86 | JMYLYV75W1J000400 |
| 87 | JMYLYV75W1J000823 |
| 88 | JMYLYV75W1J000845 |
| 89 | JMYLYV75W1J000875 |
| 90 | JMYLYV75W1J001689 |
| 91 | JMYLYV75W2J000656 |
| 92 | JMYLYV75W2J000957 |
| 93 | JMYLYV75W2J001170 |
| 94 | JMYMYV65W1J000110 |
| 95 | JMYMYV65W1J000112 |
| 96 | JMYMYV65W1J000114 |
| 97 | JMYMYV65W1J000115 |
| 98 | JMYMYV65W1J000117 |
| 99 | JMYMYV65W1J000118 |
| 100 | JMYMYV65W1J000120 |
| 101 | JMYMYV65W1J000540 |
| 102 | JMYMYV65W2J000263 |
| 103 | JMYMYV65W2J000423 |
| 104 | V65W0000670 |
| 105 | V65W0001399 |
| 106 | V65W0001409 |
| 107 | V65W0001410 |
| 108 | V65W0001411 |

| | |
|-----|-------------|
| 109 | V65W0001417 |
| 110 | V75W0002690 |
| 111 | V75W0006510 |
| 112 | V75W0006520 |
| 113 | V75W0006529 |
| 114 | V75W0006532 |