

## Recall Detail

<b>Ref No</b>	<b>10000415</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	SLK, CL-Class, S-Class
<b>Dealer (phone no)</b>	Aberdeen Service Centre: 2552 8298 Quarry Bay Service Centre: 2563 4333 Hunghom Service Centre: 2363 9396 Kwai Chung Service Centre: 2427 3355 Yuen Long Service Centre: 2473 3171
<b>Subject</b>	Replace fuel filter (4790046)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres or us at above mentioned telephone numbers to clarify whether your vehicle is affect by this recall.
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	In isolated cases the flange of the fuel filter may become leaky due to a fault in the supplier's production process. Should this occur, a fuel odor may arise or fuel may escape.
<b>Remedial Action</b>	Replace the fuel filter as a precautionary measure
<b>Build Dates</b>	04/2011 - 07/2011
<b>Launch Date</b>	28/02/2013
<b>Tentative Date of Recall Completion</b>	30/09/2013

1	WDD1724482F013442
2	WDD1724482F011216
3	WDD1724482F013510
4	WDD2163742A028447
5	WDD1724482F013912
6	WDD2211572A417283
7	WDD2211542A425570

8	WDD2211542A417817
9	WDD2211572A417291
10	WDD2211542A416900
11	WDD2211572A417716
12	WDD2211572A417012
13	WDD2211542A416853
14	WDD2211542A416493

15	WDD2211542A415179
16	WDD2211542A415108
17	WDD2211572A417810
18	WDD2211572A422745
19	WDD2211542A414834
20	WDD2211542A414540
21	WDD2211542A415275
22	WDD2211572A421317
23	WDD2211542A425563
24	WDD2211542A414430
25	WDD2211572A424113
26	WDD2211572A424086
27	WDD2211572A423654
28	WDD2211572A423566
29	WDD2211572A422454
30	WDD2211572A422360
31	WDD2211572A422079
32	WDD2211572A417875
33	WDD2211572A421302
34	WDD2211572A421292
35	WDD2211572A421177
36	WDD2211572A421000
37	WDD2211572A420986
38	WDD2211572A420955
39	WDD2211572A418163
40	WDD2211572A422316
41	WDD2211572A416946
42	WDD2211572A417757
43	WDD2211572A422852
44	WDD2211572A422782
45	WDD2211572A422462
46	WDD2211572A422322
47	WDD2211572A422304
48	WDD2211572A422045
49	WDD2211572A423324
50	WDD2211572A424260
51	WDD2211572A423497
52	WDD2211542A419531
53	WDD2211542A419492
54	WDD2211542A419414

55	WDD2211542A417129
56	WDD2211542A416923
57	WDD2211542A416866
58	WDD2211542A416427
59	WDD2211572A421015
60	WDD2211732A422628
61	WDD2163732A028451
62	WDD2163732A028284
63	WDD1724572F009500
64	WDD1724572F009494
65	WDD1724572F009488
66	WDD1724482F013076
67	WDD1724482F011213
68	WDD2211572A423305
69	WDD2211732A423491
70	WDD2211542A413896
71	WDD2211732A422379
72	WDD2211731A425856
73	WDD2211572A424950
74	WDD2211572A424042
75	WDD2211572A423579
76	WDD2211572A423552
77	WDD2211572A423516
78	WDD2211732A424266
79	WDD2211732A420157
80	WDD2211572A424563
81	WDD2211542A414185
82	WDD2211762A425801
83	WDD2211732A424763
84	WDD2211732A424079
85	WDD2211732A420118
86	WDD2211732A420081
87	WDD2211732A418133
88	WDD2211732A417979
89	WDD2211732A417843
90	WDD2211732A417709
91	WDD2211732A417698
92	WDD2211732A417560
93	WDD2211732A416995
94	WDD2211572A424899

95	WDD2211572A424628
96	WDD2211732A424507
97	WDD2211732A415951
98	WDD2211572A424635
99	WDD2211572A424814
100	WDD2211732A414306
101	WDD2211732A414327
102	WDD2211732A414615
103	WDD2211732A414361
104	WDD2211732A414412
105	WDD2211732A414444
106	WDD2211732A414566
107	WDD2211732A414347
108	WDD2211732A415595
109	WDD2211732A414971