

Recall Detail

Ref No	10000435
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Ractis
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Electric Power Steering Control Module replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to the damp coil wire in relay of the Electric Power Steering Control Module, which could have been stored without proper humidity control during the manufacturing process. If such a coil is used in the relay, moisture absorbed by the wire could condense into water droplets on certain relay terminals. Due to the insufficient distance between the terminals, the water droplets could create a bridge between the terminals and cause a short circuit. If this occurs, the control module could detect abnormal voltage in the circuit and suspend power steering assist, causing an instrument panel warning lamp to illuminate and a buzzer to sound. Suspension of power steering assist results in increased steering effort and increases the risk of a crash at low speeds.
Remedial Action	Replace Electric Power Steering Control Module
Build Dates	August 2010 – August 2011
Launch Date	3 July 2013
Tentative Date of Recall Completion	December 2018

1	JTDKT9C3001000178
2	JTDKT9C3001000293
3	JTDKT9C3001000634
4	JTDKT9C3001000696
5	JTDKT9C3001000715
6	JTDKT9C3101000254
7	JTDKT9C3101000349
8	JTDKT9C3101000402
9	JTDKT9C3101000707
10	JTDKT9C3201000117
11	JTDKT9C3201000134
12	JTDKT9C3201000151
13	JTDKT9C3201000313
14	JTDKT9C3201000361
15	JTDKT9C3201000392
16	JTDKT9C3201000540
17	JTDKT9C3201000571
18	JTDKT9C3201000781

19	JTDKT9C3301000157
20	JTDKT9C3301000305
21	JTDKT9C3301000434
22	JTDKT9C3301000515
23	JTDKT9C3301000563
24	JTDKT9C3401000152
25	JTDKT9C3401000216
26	JTDKT9C3401000605
27	JTDKT9C3501000161
28	JTDKT9C3501000208
29	JTDKT9C3501000287
30	JTDKT9C3501000404
31	JTDKT9C3501000662
32	JTDKT9C3501000693
33	JTDKT9C3601000198
34	JTDKT9C3601000556
35	JTDKT9C3701000288
36	JTDKT9C3701000761

37	JTDKT9C3801000154
38	JTDKT9C3801000235
39	JTDKT9C3801000378
40	JTDKT9C3801000381
41	JTDKT9C3801000493
42	JTDKT9C3801000526
43	JTDKT9C3901000194
44	JTDKT9C3901000213
45	JTDKT9C3901000230
46	JTDKT9C3901000292
47	JTDKT9C3901000390
48	JTDKT9C3901000583
49	JTDKT9C3901000678
50	JTDKT9C3X01000219
51	JTDKT9C3X01000348
52	JTDKT9C3X01000611
53	JTDKT9C3X01000642