

Voluntary Recall Detail

Ref No	10000451
Manufacturer	AUDI
Vehicle Class	Private Car
Model/Type	A1 / A3 / TT
Dealer (phone no)	Premium Motors Ltd. (3465 0000)
Subject	Voluntary Recall: Replacing gear oil
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	On Audi vehicles with 7-speed dual clutch gearbox (DSG) manufactured within a specific period, conductive deposits may form in the gearbox control unit (due to electrolysis). These may cause short circuits and cause the gearbox fuse to blow. The clutches open due to the power supply failure and the vehicle will roll to a stop. The function of all the other vehicle systems (engine, steering, brakes, lights) is unaffected.
Remedial Action	On the vehicles affected, the gear oil must be replaced and a software update must be carried out for the gearbox control unit.
Build Dates	Model Year: 2013 - 2014
Launch Date	2 December 2013
Tentative Date of Recall Completion	2 December 2014

1	TRUZZZ8J1D1012646
2	TRUZZZ8J2D1015801
3	TRUZZZ8J5D1016120
4	TRUZZZ8J7D1016457
5	TRUZZZ8J5D1016683
6	WAUZZZ8X6DB053635
7	WAUZZZ8X6DB097425
8	WAUZZZ8X2DB103995
9	WAUZZZ8X0DB105406
10	WAUZZZ8X5DB105949
11	WAUZZZ8X9DB105968

12	WAUZZZ8X4DB106347
13	WAUZZZ8X4DB106669
14	WAUZZZ8X8DB106917
15	WAUZZZ8X3DB107277
16	WAUZZZ8X0DB107589
17	WAUZZZ8X4DB107773
18	WAUZZZ8X1DB108072
19	WAUZZZ8XXDB108569
20	WAUZZZ8XXDB109687
21	WAUZZZ8X5DB109760
22	WAUZZZ8X4DB110074

23	WAUZZZ8X9DB110099
24	WAUZZZ8X5DB110441
25	WAUZZZ8X4DB110611
26	WAUZZZ8X0DB110668
27	WAUZZZ8X9DB111415
28	WAUZZZ8XXDB111813
29	WAUZZZ8X1DB115894
30	WAUZZZ8X0DB116082
31	WAUZZZ8X3DB119798