

### Recall Detail

<b>Ref No</b>	<b>10000467</b>
<b>Manufacturer</b>	BMW
<b>Vehicle Class</b>	Motor Cycle
<b>Model/Type</b>	C 600 Sport, C 650 GT, F 700 GS, F 800 GS, F 800 GT, R 1200 R, R 1200 GS
<b>Dealer (phone no)</b>	31936688
<b>Subject</b>	Side-stand switch
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below: (Last Seven Numbers)
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Within the framework of quality monitoring, BMW Motorrad has ascertained that the side-stand switches are not correctly sealed. In rare cases water penetrating inside the switch can cause the side-stand switch to malfunction. The possibility of this malfunction causing the engine to die while the vehicle is on the move cannot be precluded.
<b>Remedial Action</b>	Replacing the side-stand switches
<b>Build Dates</b>	11/2012 – 10/2013
<b>Launch Date</b>	27/02/2014
<b>Tentative Date of Recall Completion</b>	31/08/2014

1	<b>Z005141</b>
2	<b>Z005313</b>
3	<b>Z005491</b>
4	<b>Z008371</b>
5	<b>Z008465</b>
6	<b>Z008476</b>
7	<b>Z008480</b>
8	<b>Z008481</b>
9	<b>Z008531</b>
10	<b>Z008532</b>
11	<b>Z008603</b>
12	<b>Z048770</b>
13	<b>Z128651</b>
14	<b>Z128657</b>
15	<b>Z128691</b>
16	<b>Z128699</b>
17	<b>Z300406</b>
18	<b>Z301296</b>
19	<b>Z301592</b>

20	<b>Z301683</b>
21	<b>Z301932</b>
22	<b>Z301933</b>
23	<b>Z301999</b>
24	<b>Z302000</b>
25	<b>ZY83835</b>
26	<b>ZY84001</b>
27	<b>ZY84980</b>
28	<b>ZZ50249</b>
29	<b>ZZ50250</b>
30	<b>ZZ50617</b>
31	<b>ZZ50781</b>
32	<b>ZZ50782</b>
33	<b>ZZ50876</b>
34	<b>ZZ50881</b>
35	<b>ZZ50882</b>
36	<b>ZZ50906</b>
37	<b>ZZ51382</b>
38	<b>ZZ51428</b>

39	<b>ZZ51429</b>
40	<b>ZZ51492</b>
41	<b>ZZ51534</b>
42	<b>ZZ51535</b>
43	<b>ZZ52080</b>
44	<b>ZZ52081</b>
45	<b>ZZ52373</b>
46	<b>ZZ52374</b>
47	<b>ZZ52389</b>
48	<b>ZZ52390</b>
49	<b>ZZ69501</b>
50	<b>ZZ70043</b>
51	<b>ZZ70268</b>
52	<b>ZZ70269</b>
53	<b>ZZ70270</b>
54	<b>ZZ70271</b>
55	<b>ZZ70401</b>
56	<b>ZZ70576</b>
57	<b>ZZ70609</b>
58	<b>ZZ71121</b>
59	<b>ZZ71171</b>
60	<b>ZZ71176</b>
61	<b>ZZ71177</b>
62	<b>ZZ71651</b>
63	<b>ZZ71652</b>
64	<b>ZZ71685</b>
65	<b>ZZ71686</b>
66	<b>ZZ71820</b>
67	<b>ZZ71967</b>
68	<b>ZZ72259</b>
69	<b>ZZ72293</b>
70	<b>ZZ72294</b>
71	<b>ZZ80164</b>
72	<b>ZZ83491</b>