| Recall Detail | | |
|--|---|--|
| Ref No | 10000471 | |
| Manufacturer | Toyota | |
| Vehicle Class | Private Car | |
| Model/Type | Ractis | |
| Dealer (phone no) | Crown Motors Limited (Tel: 2880 4988) | |
| Subject | Replacement of Starter Relay and Starter Assembly | |
| Progress | Running | |
| Affected Vehicle Identification Number (VIN) | List as below: | |
| Description of Defect, how it came to light, and possible consequences if ignored. | Due to the improper design of the starter system circuit in which the starter relay may cause the starter to be operated improperly, which could result in damage of the starter and increase the risk of a fire. | |
| Remedial Action | Replace starter relay and starter assembly | |
| Build Dates | April 2013 - August 2013 | |
| Launch Date | 9 April 2014 | |
| Tentative Date of Recall Completion | December 2016 | |

| 1 | JTDKT9C3101003462 |
|----|-------------------|
| 2 | JTDKT9C3101003560 |
| 3 | JTDKT9C3201003647 |
| 4 | JTDKT9C3201003714 |
| 5 | JTDKT9C3401003469 |
| 6 | JTDKT9C3501003691 |
| 7 | JTDKT9C3501003772 |
| 8 | JTDKT9C3701003465 |
| 9 | JTDKT9C3801003796 |
| 10 | JTDKT9C3901003435 |
| 11 | JTDKT9C3901003502 |
| 12 | JTDKT9C3X01003539 |
| 13 | JTDKT9C3X01003573 |
| 14 | JTDKT9C3X01003590 |