

Recall Detail

Ref No	10000494
Manufacturer	Infiniti
Vehicle Class	Private Car
Model/Type	M35H (Y51) Q70L (Y51) Q50S (V37)
Dealer (phone no)	Honest Motors Ltd. (Tel: 22168228)
Subject	Reprogramming of ECM
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The program in the ECM may run inappropriately on very rare occasions if a signal from the throttle position sensor of electric throttle control actuator is in trouble. As a result, the vehicle may accelerate gradually without regard to the intention.
Remedial Action	Reprogram ECM
Build Dates	M35H (Y51): 02-JUL-2012 to 06-FEB-2013 Q70L (Y51): 11-NOV-2013 to 17-MAR-2014 Q50 (V37): 24-FEB-2014 to 03-JUN-2014
Launch Date	30/09/2014
Tentative Date of Recall Completion	30/09/2015

M35H (Y51)

1.	JN1BEAY51Z0440002	4.	JN1BEAY51Z0440007
2.	JN1BEAY51Z0440003	5.	JN1BEAY51Z0440008
3.	JN1BEAY51Z0440004	6.	JN1BEAY51Z0440009

Q70L (Y51)

1.	JN1CEAY51Z0100001	17.	JN1CEAY51Z0100018
2.	JN1CEAY51Z0100002	18.	JN1CEAY51Z0100019
3.	JN1CEAY51Z0100003	19.	JN1CEAY51Z0100020
4.	JN1CEAY51Z0100005	20.	JN1CEAY51Z0100021
5.	JN1CEAY51Z0100006	21.	JN1CEAY51Z0100022
6.	JN1CEAY51Z0100007	22.	JN1CEAY51Z0100023
7.	JN1CEAY51Z0100008	23.	JN1CEAY51Z0100024
8.	JN1CEAY51Z0100009	24.	JN1CEAY51Z0100025
9.	JN1CEAY51Z0100010	25.	JN1CEAY51Z0100026
10.	JN1CEAY51Z0100011	26.	JN1CEAY51Z0100027
11.	JN1CEAY51Z0100012	27.	JN1CEAY51Z0100028
12.	JN1CEAY51Z0100013	28.	JN1CEAY51Z0100029
13.	JN1CEAY51Z0100014	29.	JN1CEAY51Z0100030
14.	JN1CEAY51Z0100015	30.	JN1CEAY51Z0100031
15.	JN1CEAY51Z0100016	31.	JN1CEAY51Z0100032
16.	JN1CEAY51Z0100017	32.	JN1CEAY51Z0100033

Q50S (V37)

1.	JN1BAAV37Z0470004	6.	JN1BAAV37Z0470009
2.	JN1BAAV37Z0470005	7.	JN1BAAV37Z0470010
3.	JN1BAAV37Z0470006	8.	JN1BAAV37Z0470011
4.	JN1BAAV37Z0470007	9.	JN1BAAV37Z0470013
5.	JN1BAAV37Z0470008	10.	JN1BAAV37Z0470014