

Recall Detail	
Ref No	10000564
Manufacturer	BMW
Vehicle Class	Motor Cycle
Model/Type	C 600 Sport, C 650 GT
Dealer (phone no)	31936688
Subject	Front brake hose
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	BMW Motorrad has ascertained that the flexibility of a front brake hose can be impaired if the positioning of the abrasion protection is poor. This can result in the brake hose suffering damage, which could subsequently lead to an escape of brake fluid. The stopping power of the front brake would diminish, depending on the amount of fluid lost in this way.
Remedial Action	Renew the brake hose
Build Dates	02/2011 – 07/2015
Launch Date	11/12/2015
Tentative Date of Recall Completion	30/06/2016

1	ZD90274
2	ZZ47574
3	ZZ47668
4	ZZ47669
5	ZZ48121
6	ZZ48122
7	ZZ48126
8	ZZ48158
9	ZZ48420
10	ZZ48431
11	ZZ48432
12	ZZ48906
13	ZZ49197
14	ZZ49231
15	ZZ49264
16	ZZ49311
17	ZZ50249
18	ZZ50250
19	ZZ50617
20	ZZ50781

21	ZZ50782
22	ZZ50876
23	ZZ50881
24	ZZ50882
25	ZZ50906
26	ZZ51382
27	ZZ51428
28	ZZ51429
29	ZZ51492
30	ZZ51534
31	ZZ51535
32	ZZ52080
33	ZZ52081
34	ZZ52389
35	ZZ52390
36	ZZ52464
37	ZZ52466
38	ZZ55873
39	ZZ65833
40	ZZ66952

41	ZZ66957
42	ZZ66959
43	ZZ66960
44	ZZ66961
45	ZZ66962
46	ZZ66963
47	ZZ66964
48	ZZ66965
49	ZZ66966
50	ZZ66967
51	ZZ66968
52	ZZ66969
53	ZZ66975
54	ZZ66976
55	ZZ66978
56	ZZ67104
57	ZZ67105
58	ZZ67117
59	ZZ67161
60	ZZ67167
61	ZZ67168
62	ZZ67169
63	ZZ67170
64	ZZ67390
65	ZZ67394
66	ZZ67395
67	ZZ67396
68	ZZ67632
69	ZZ67634
70	ZZ67635
71	ZZ69501
72	ZZ70043
73	ZZ70268
74	ZZ70269
75	ZZ70270
76	ZZ70271
77	ZZ70401
78	ZZ70576
79	ZZ70609
80	ZZ71121
81	ZZ71171

82	ZZ71176
83	ZZ71177
84	ZZ71651
85	ZZ71652
86	ZZ71685
87	ZZ71686
88	ZZ71820
89	ZZ71967
90	ZZ72259
91	ZZ72293
92	ZZ72294
93	ZZ72424
94	ZZ72429
95	ZZ72430
96	ZZ72762
97	ZZ72766