Recall Detail		
Ref No	10000650	
Manufacturer	Subaru	
Vehicle Class	Private Car	
Model/Type	1.6L DIT Levorg	
Dealer (phone no)	Motor Image Kowloon Limited (23936118)	
Subject	Reprogramming of the Engine Control Unit (ECU)	
Progress	Running	
Affected Vehicle Identification Number (VIN)	List as below:	
Description of Defect, how it came to light, and possible consequences if ignored.	The defect is due to an inappropriate programming of the Engine Control Unit (ECU). When the intake air temperature is high, the ignition timing, fuel injection and/or boost pressure may not be controlled properly which may result in abnormal combustion. If abnormal combustion occurs, it may cause a connecting rod to break due to the abnormal high pressure in a cylinder. In the worst case scenario, a cylinder block may be damaged, leading to engine oil leakage that may results in a fire.	
Remedial Action	Reprogramming of the Engine Control Unit (ECU)	
Build Dates	2016-2017	
Launch Date	6 March 2017	
Tentative Date of Recall Completion	31 December 2018	

<u> </u>	
1	JF1VM4K55GG002244
2	JF1VM4K55GG002423
3	JF1VM4K55GG002417
4	JF1VM4K55GG002490
5	JF1VM4K55GG002430
6	JF1VM4K55GG002259
7	JF1VM4K55GG002459
8	JF1VM4K55GG002422
9	JF1VM4K55GG002450
10	JF1VM4K55GG002432
11	JF1VM4K55GG002427
12	JF1VM4K55GG002503
13	JF1VM4K55GG002414
14	JF1VM4K55GG002506
15	JF1VM4K55GG002489
16	JF1VM4K55GG002282
17	JF1VM4K55GG002486
18	JF1VM4K55GG002471

19	JF1VM4K55GG002322
20	JF1VM4K55GG002476
21	JF1VM4K55GG002253
22	JF1VM4K55GG002418
23	JF1VM4K55GG002426
24	JF1VM4K55GG002465
25	JF1VM4K55GG002491
26	JF1VM4K55GG002324
27	JF1VM4K55GG002320
28	JF1VM4K55HG003795
29	JF1VM4K55GG002267
30	JF1VM4K55GG002498
31	JF1VM4K55GG002492
32	JF1VM4K55GG002275
33	JF1VM4K55GG002316
34	JF1VM4K55GG002504
35	JF1VM4K55GG002494
36	JF1VM4K55GG002446
•	_

JF1VM4K55GG002507
JF1VM4K55GG002497
JF1VM4K55GG002263
JF1VM4K55GG002161
JF1VM4K55GG002319
JF1VM4K55GG002325
JF1VM4K55GG002420
JF1VM4K55GG002456
JF1VM4K55GG002225
JF1VM4K55GG002493
JF1VM4K55GG002481
JF1VM4K55GG002505
JF1VM4K55GG002235
JF1VM4K55GG002508
JF1VM4K55GG002500