

## Recall Detail

<b>Ref No</b>	<b><u>10000661</u></b>
<b>Manufacturer</b>	AUDI
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	A4 (8W)
<b>Dealer (phone no)</b>	Premium Motors Ltd (3465 0000)
<b>Subject</b>	Servicing seat belt tensioners
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	On Audi vehicles manufactured within a specific period, there are irregularities in the mix ratio of the igniting agent in some seat belt tensioners which could lead to the seat belt tensioners not triggering in the event of an accident.
<b>Remedial Action</b>	The seat belt tensioners affected must be replaced on the corresponding vehicles.
<b>Build Dates</b>	Model Year: 2017
<b>Launch Date</b>	20 March 2017
<b>Tentative Date of Recall Completion</b>	20 March 2018

1	WAUZZZF42HA037002	13	WAUZZZF43HA043407
2	WAUZZZF41HA037119	14	WAUZZZF48HA043497
3	WAUZZZF42HA040837	15	WAUZZZF41HA043549
4	WAUZZZF43HA040961	16	WAUZZZF43HA043584
5	WAUZZZF46HA041067	17	WAUZZZF41HA043969
6	WAUZZZF42HA041616	18	WAUZZZF46HA043983
7	WAUZZZF47HA041837	19	WAUZZZF47HA044236
8	WAUZZZF4XHA042125	20	WAUZZZF41HA044488
9	WAUZZZF47HA042972	21	WAUZZZF44HA044565
10	WAUZZZF40HA043283	22	WAUZZZF48HA044908
11	WAUZZZF49HA043315	23	WAUZZZF48HA045105
12	WAUZZZF42HA043351	24	WAUZZZF4XHA045137

25	WAUZZZF40HA045289
26	WAUZZZF40HA045907
27	WAUZZZF40HA058432
28	WAUZZZF45HA061407
29	WAUZZZF4XHA061421