

Recall Detail

Ref No	10000689
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Echo
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Replacement of Driver's side Frontal Airbag Inflator (Re-Notification)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The recall is related to the driver's side frontal air bag inflators which could have been assembled with improperly manufactured propellant wafers. Improperly manufactured propellant wafers could cause the inflator to rupture. In the case of a collision, the driver's side frontal air bag will be deployed abnormally which could result in increase of the risk of injury to the occupant.
Remedial Action	Replace driver's side frontal airbag inflator
Build Dates	December 2002 ~ November 2003
Launch Date	March 2017
Tentative Date of Recall Completion	December 2018

1	JTDKW123000191830
2	JTDKW123000197398
3	JTDKW123003111683
4	JTDKW123003112073
5	JTDKW123100191318
6	JTDKW123100191366
7	JTDKW123100191528
8	JTDKW123100191559
9	JTDKW123100191576
10	JTDKW123100192856
11	JTDKW123100194090
12	JTDKW123100199290
13	JTDKW123100210238
14	JTDKW123103111580
15	JTDKW123200191599
16	JTDKW123200192770
17	JTDKW123200193692
18	JTDKW123200196737
19	JTDKW123200210121
20	JTDKW123200210250
21	JTDKW123200210605

22	JTDKW123203111782
23	JTDKW123203112110
24	JTDKW123300191059
25	JTDKW123300191272
26	JTDKW123300191403
27	JTDKW123300193863
28	JTDKW123300197590
29	JTDKW123300199436
30	JTDKW123300210726
31	JTDKW123300211732
32	JTDKW123400191264
33	JTDKW123400191457
34	JTDKW123400210492
35	JTDKW123400210931
36	JTDKW123400210959
37	JTDKW123400211187
38	JTDKW123403111637
39	JTDKW123403111671
40	JTDKW123403111699
41	JTDKW123403112044
42	JTDKW123500191175

43	JTDKW123500191208
44	JTDKW123500191323
45	JTDKW123500192553
46	JTDKW123500192746
47	JTDKW123500198952
48	JTDKW123500211392
49	JTDKW123500211747
50	JTDKW123503111582
51	JTDKW123503111601
52	JTDKW123503111663
53	JTDKW123503111727
54	JTDKW123503112019
55	JTDKW123600191248
56	JTDKW123600191427
57	JTDKW123600191606
58	JTDKW123600191623
59	JTDKW123600191718
60	JTDKW123600192514
61	JTDKW123600199852
62	JTDKW123600210056
63	JTDKW123600210798
64	JTDKW123600211059
65	JTDKW123600211112
66	JTDKW123600211238
67	JTDKW123603111560
68	JTDKW123603111610
69	JTDKW123603111655
70	JTDKW123603111770
71	JTDKW123603112062
72	JTDKW123700191548
73	JTDKW123700192991
74	JTDKW123700193297
75	JTDKW123700197074
76	JTDKW123700210504
77	JTDKW123700211524
78	JTDKW123703111924
79	JTDKW123703112135
80	JTDKW123800191073
81	JTDKW123800191140
82	JTDKW123800191221
83	JTDKW123800192661

84	JTDKW123803111575
85	JTDKW123803111589
86	JTDKW123803111740
87	JTDKW123803111902
88	JTDKW123803111950
89	JTDKW123803111981
90	JTDKW123803112144
91	JTDKW123900191048
92	JTDKW123900191101
93	JTDKW123900191177
94	JTDKW123900191485
95	JTDKW123900191633
96	JTDKW123900199876
97	JTDKW123903111567
98	JTDKW123903111598
99	JTDKW123903111617
100	JTDKW123903111620
101	JTDKW123903111780
102	JTDKW123903112086
103	JTDKW123X00193410
104	JTDKW123X00197134
105	JTDKW123X00210142
106	JTDKW123X00211467
107	JTDKW123X03111626
108	JTDKW123X03111755
109	JTDKW123X03111853
110	JTDKW123000196770