

Recall Detail

Ref No	10000710
Manufacturer	ASTON MARTIN
Vehicle Class	PRIVATE CAR
Model/Type	V8 Vantage, V8 Vantage S (7-speed SportShift II Transmission)
Dealer (phone no)	MF Jebsen Automotive Limited (2234 0562)
Subject	Connector Failure on Transmission
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	A connector in the hydraulic system for the 7-speed Auto-Shift Manual (ASM) transmission that is installed on V8 Vantage, was found not to have sufficient support. The connector is between the pipe for the clutch fluid and the ASM system. It is possible that this connector can fail and cause loss of the clutch fluid. This would result in malfunction of the clutch system, which could cause a vehicle crash.
Remedial Action	If necessary, a support bracket will be installed to hold the pipe securely in position and prevent movement of the assembly.
Build Dates	Manufactured from Jul 2010 – Sep 2013
Launch Date	14 July 2017
Tentative Date of Recall Completion	April 2018

1	SCFGJBDL7BGC15174
2	SCFGJBDL2BGC15177
3	SCFGJBDL0BGC15324
4	SCFGJBDL2BGC15325
5	SCFGJBDL8BGC15328
6	SCFGJBDL6BGC15392
7	SCFGJBDL8BGC15393
8	SCFEJBDL1CGC15793
9	SCFGJBDL4CGC15795
10	
11	
12	
13	
14	
15	
16	
17	

18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	