

Recall Detail

Ref No	10000715
Manufacturer	Volvo
Vehicle Class	Private Car
Model/Type	XC90 T6
Dealer (phone no)	29273399
Subject	Seat Belt (Right hand side in the third row passenger seat)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Seat belt pre-tensioner may have been produced with an incorrect production parameter, a very small part of the pre-tensioner may detach during a crash event and could enter into the luggage compartment.
Remedial Action	Replace the seat belt on the right hand side, in the third seat row
Build Dates	2016
Launch Date	10 July 2017
Tentative Date of Recall Completion	31 January 2018

1	YV1LFA2ACH1135584
2	YV1LFA2ACH1135673
3	YV1LFA2ACH1135797
4	YV1LFA2ACH1135808
5	YV1LFA2ACH1135864
6	YV1LFA2ACH1136000
7	YV1LFA2ACH1136176
8	YV1LFA2ACH1136199
9	YV1LFA2ACH1136247
10	YV1LFA2ACH1136315
11	YV1LFA2ACH1138168
12	YV1LFA2ACH1138174
13	YV1LFA2BCH1140314
14	YV1LFA2BCH1140330
15	YV1LFA2BCH1140401