

Recall Detail

Ref No	10000722
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	smart fortwo / 453
Dealer (phone no)	Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Yuen Long Service Centre: 2473 3171
Subject	Check adjusting nut of parking brake, replace if necessary (4293031)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The travel of the hand brake lever of affected vehicles may gradually lengthen by way of actuation due to a loosening lock nut of the hand brake cable.</p> <p>If the travel of the hand brake lever lengthens, it may be possible that the parking brake does not exert the force required to sufficiently secure the vehicle in all situations. Subsequently, the vehicle could start to move unintentionally on a downward slope in the event of a fault. This could increase the risk of an accident occurring.</p>
Remedial Action	Check the adjusting nut of the parking brake on affected vehicles as a precautionary measure and replace it if necessary.
Build Dates	02/07/2015 - 26/10/2015
Launch Date	21/08/2017
Tentative Date of Recall Completion	31/12/2017

3	WME4533422K034895
4	WME4533422K034911
5	WME4533422K034918
6	WME4533422K051601
7	WME4533422K063857
8	WME4533422K063889
9	WME4533422K063920
10	WME4533422K063984
11	WME4533422K063993
12	WME4533422K064022
13	WME4533422K064047
14	WME4533422K064072
15	WME4533422K064115
16	WME4533422K064175
17	WME4533422K064200
18	WME4533422K064231
19	WME4533422K064285
20	WME4533422K064336
21	WME4533422K064381
22	WME4533422K064441
23	WME4533422K064447
24	WME4533422K064454
25	WME4533422K064458
26	WME4533422K064540
27	WME4533422K064575
28	WME4533422K064596
29	WME4533422K064599
30	WME4533422K064648
31	WME4533422K064662
32	WME4533422K064669
33	WME4533422K064675
34	WME4533422K064693
35	WME4533422K064711
36	WME4533422K064753
37	WME4533422K064794
38	WME4533422K064808
39	WME4533422K064818
40	WME4533422K064889
41	WME4533422K064940
42	WME4533422K064960

43	WME4533422K064982
44	WME4533422K065099
45	WME4533422K065127
46	WME4533422K065151
47	WME4533422K065176
48	WME4533422K065183
49	WME4533422K065199
50	WME4533422K065205
51	WME4533422K065216
52	WME4533422K065277
53	WME4533422K065301
54	WME4533422K065326
55	WME4533422K065334
56	WME4533422K065349
57	WME4533422K065379
58	WME4533422K065415
59	WME4533422K065424
60	WME4533422K065428
61	WME4533422K065445
62	WME4533422K065478
63	WME4533422K065581
64	WME4533422K065673
65	WME4533422K065754
66	WME4533422K065802
67	WME4533422K065806
68	WME4533422K066866
69	WME4533422K066928
70	WME4533422K066997
71	WME4533422K067009
72	WME4533422K067495
73	WME4533422K067671