

## Recall Detail

<b>Ref No</b>	<b>10000805</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	C-Class / 205
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Quarry Bay Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Check beltline trim strip at left and right, replace if necessary (7291137)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The bonding of the rear beltline trim strip at the left and right in affected vehicles may not have been executed correctly.  As a result, the aluminum section of this trim strip could become detached from the affected vehicle when it is driven. Consequently, this may present a hazard to any traffic following behind.
<b>Remedial Action</b>	Check the trim strips on your vehicle as a precautionary measure and replace them if necessary.
<b>Build Dates</b>	23/06/2016 - 29/09/2017
<b>Launch Date</b>	29/08/2018
<b>Tentative Date of Recall Completion</b>	31/12/2018

1	WDD2054422F381162
2	WDD2054422F394933
3	WDD2054422F446572

4	WDD2054422F447915
5	WDD2054422F450686
6	WDD2054422F452554

7	WDD2054422F452807
8	WDD2054422F454509
9	WDD2054422F455132
10	WDD2054422F455172
11	WDD2054422F455337
12	WDD2054422F458264
13	WDD2054422F459076
14	WDD2054422F461415
15	WDD2054422F462807
16	WDD2054422F464346
17	WDD2054422F464781
18	WDD2054422F465066
19	WDD2054422F465932
20	WDD2054422F468078
21	WDD2054422F468089
22	WDD2054422F468251
23	WDD2054422F468415
24	WDD2054422F469425
25	WDD2054422F470621
26	WDD2054422F470739
27	WDD2054422F472462
28	WDD2054422F473857
29	WDD2054422F473932
30	WDD2054422F474990
31	WDD2054422F476721
32	WDD2054422F487462
33	WDD2054422F504961
34	WDD2054422F513921
35	WDD2054422F519460
36	WDD2054422F551231
37	WDD2054422F555727
38	WDD2054422F563095
39	WDD2054422F563411
40	WDD2054422F566625
41	WDD2054422F566910
42	WDD2054422F579718
43	WDD2054422F581824
44	WDD2054422F587303
45	WDD2054422F589898
46	WDD2054422F590644

47	WDD2054422F595538
48	WDD2054422F599549
49	WDD2054422F610177
50	WDD2054422F610675
51	WDD2054422F611861
52	WDD2054422F630387
53	WDD2054422F647141
54	WDD2054422F648125
55	WDD2054422F653811
56	WDD2054452F394934
57	WDD2054452F394935
58	WDD2054481F560982
59	WDD2054482F443880
60	WDD2054482F447542
61	WDD2054482F452182
62	WDD2054482F458868
63	WDD2054482F466384
64	WDD2054482F466757
65	WDD2054482F467973
66	WDD2054482F468276
67	WDD2054482F485612
68	WDD2054482F487939
69	WDD2054482F553665
70	WDD2054482F592620
71	WDD2054642F418723
72	WDD2054642F439498
73	WDD2054642F448394
74	WDD2054642F448613
75	WDD2054642F455205
76	WDD2054642F455324
77	WDD2054642F455444
78	WDD2054642F459979
79	WDD2054642F474357
80	WDD2054642F476051
81	WDD2054642F498305
82	WDD2054642F498874
83	WDD2054642F553238
84	WDD2054642F622322
85	WDD2054642F632485
86	WDD2054862F460095

87	WDD2054862F461309
88	WDD2054872F451648