

Recall Detail

Ref No	10000842
Manufacturer	Bentley
Vehicle Class	Private car
Model/Type	Mulsanne / Mulsanne Speed
Dealer (phone no)	Ap Lei Chau Service Center Tel: 25537713 Tsuen Wan Service Center Tel: 21119679 Kowloon Bay Service Center Tel: 22621288
Subject	Mulsanne - Rear seat belt anchor plate installation
Progress	In process
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The body mounting panels of the seat belt buckle anchorages used had been manufactured using an incorrect grade of material by the supplier. Testing in September 2018 identified that the rear seat belt anchorage performance may not fulfil the load requirements.
Remedial Action	An additional reinforcement plate will be fitted to the body structure to improve the strength of the rear seat belt mounting in the vehicle.
Build Dates	Model Year: From 2012 to 2019
Launch Date	21 Jan 2019
Tentative Date of Recall Completion	20 Jan 2020

1	SCBBA63Y0CC017039
2	SCBBA63YXCC017064
3	SCBBA63Y0CC017106
4	SCBBA63Y9CC017153
5	SCBBA63YXCC017162
6	SCBBA63Y7CC017197
7	SCBBA63Y0CC017252
8	SCBBA63YXCC017257
9	SCBBA63Y2DC017397
10	SCBBA63Y6DC017399
11	SCBBA63Y6DC017421
12	SCBBA63Y6DC017435
13	SCBBA63Y3DC017439
14	SCBBA63Y5DC017443
15	SCBBA63Y7DC017461
16	SCBBA63Y7DC017492
17	SCBBA63Y6DC017516

18	SCBBA63Y3DC017599
19	SCBBA63Y9DC017607
20	SCBBA63Y1DC017746
21	SCBBA63Y7DC017816
22	SCBBA63Y9DC017834
23	SCBBA63Y3DC017991
24	SCBBA63Y6DC017998
25	SCBBA63Y0DC018077
26	SCBBA63Y7DC018111
27	SCBBA63Y1DC018153
28	SCBBA63Y9DC018188
29	SCBBA63Y7DC018223
30	SCBBA63Y2DC018243
31	SCBBA63Y6DC018326
32	SCBBA63Y0DC018337
33	SCBBA63Y9DC018384
34	SCBBA63Y4DC018423

35	SCBBA63Y7DC018545
36	SCBBA63Y2DC018582
37	SCBBA63Y0EC001006
38	SCBBA63Y2EC001007
39	SCBBA63Y0EC001054
40	SCBBA63Y2EC018602
41	SCBBA63Y6EC018604
42	SCBBA63Y1EC018624
43	SCBBA63Y7EC018675
44	SCBBA63Y3EC018978
45	SCBBA63Y7EC018983
46	SCBBA63Y2EC018986
47	SCBBA63Y2EC019684
48	SCBBA63Y8EC019687
49	SCBBA63Y6EC019784
50	SCBBA63Y3EC019791
51	SCBBA63Y5EC019890
52	SCBBA63Y9EC019892
53	SCBBA63Y7FC001117
54	SCBBA63Y5FC001133
55	SCBBA63Y6FC001173
56	SCBBA63Y3FC001177
57	SCBBA63Y9FC001183
58	SCBBA63Y0FC001217
59	SCBBA63Y8FC001224
60	SCBBA63Y3FC001227
61	SCBBA63Y8FC001241
62	SCBBA63Y9FC001264
63	SCBBA63Y6FC001268
64	SCBBA63YXFC001273
65	SCBBA63Y3FC001275
66	SCBBA63Y9FC001278
67	SCBBA63Y6FC001285
68	SCBBA63Y1FC001291
69	SCBBA63Y5FC001293
70	SCBBA63Y9FC001295
71	SCBBD63Y4GC001486
72	SCBBD63Y8GC001488
73	SCBBD63Y0GC001498
74	SCBBD63Y4GC001519
75	SCBBD63Y8GC001524

76	SCBBD63Y1GC001719
77	SCBBD63Y0GC001775
78	SCBBE63Y2GC001967
79	SCBBE63Y4GC002201
80	SCBBE63Y8GC002248
81	SCBBE63Y8GC002587
82	SCBBE63Y1GC002608
83	SCBBM63Y3HC003005
84	SCBBM63Y9HC003056
85	SCBBM63Y6HC003077
86	SCBBM63YXHC003079
87	SCBBM63Y9HC003087
88	SCBBM63Y5HC003099
89	SCBBM63Y4HC003319
90	SCBBM63YXJC003363
91	SCBBM63Y2JC003406
92	SCBBM63Y7JC003417
93	SCBBM63Y2JC003440
94	SCBBM63Y8JC003524
95	SCBBN63Y4JC003579
96	SCBBM63Y2JC003583
97	SCBBM63Y7JC003708
98	SCBBM63Y0JC003713