

## Recall Detail

<b>Ref No</b>	<b>10000854</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	C-Class, GLC-Class & S-Class / 205, 253 & 222
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Replace seat belt buckles (9190301)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The switches in certain seat belt buckles on affected vehicles may have been manufactured outside of the specification. Because of this, it is possible that while in operation, the vehicle may mistakenly detect a correctly engaged seat belt as being not engaged. A warning tone and a warning symbol in the instrument cluster inform the driver of this condition.</p> <p>In the event of an accident, the result would be that the seat belt tensioner would not be activated correctly. Because of this, the complete effect of the restraint system could not be ensured. This would pose an increased risk of injury for the vehicle occupants.</p>
<b>Remedial Action</b>	Replace the affected seat belt buckles on affected vehicles as a precautionary measure.
<b>Build Dates</b>	20/06/2018 - 06/09/2018
<b>Launch Date</b>	25/02/2019
<b>Tentative Date of Recall Completion</b>	31/12/2019

3	WDD2053772F787225
4	WDD2053772F787527
5	WDD2053772F787565
6	WDD2053772F787955
7	WDD2053772F789015
8	WDD2053772F789110
9	WDD2053772F789154
10	WDD2053772F789301
11	WDD2053772F790222
12	WDD2053772F790787
13	WDD2053772F792001
14	WDD2053772F792581
15	WDD2053772F794045
16	WDD2053772F794194
17	WDD2053772F794252
18	WDD2053772F794305
19	WDD2053772F796575
20	WDD2053772F797555
21	WDD2053772F798133
22	WDD2053832F773808
23	WDD2053832F774756
24	WDD2053832F775415
25	WDD2053832F788146
26	WDD2053832F793408
27	WDD2053832F793745
28	WDD2053832F794401
29	WDD2053832F796018
30	WDD2053832F796176
31	WDD2053832F796558
32	WDD2053832F796816
33	WDD2054642F798114
34	WDD2054772F772205
35	WDD2054772F787858
36	WDD2054772F791106
37	WDD2054772F794327
38	WDD2054772F795155
39	WDD2054832F774638
40	WDD2054832F774718
41	WDD2054832F792435
42	WDD2221602A434222

43	WDD2221602A435653
44	WDD2221602A435859
45	WDD2221602A436636
46	WDD2221602A436972
47	WDD2221602A437003
48	WDD2221602A438329
49	WDD2221602A438450
50	WDD2221602A438667
51	WDD2221602A438934
52	WDD2221602A438972
53	WDD2221602A439091
54	WDD2221602A439148
55	WDD2221602A439174
56	WDD2221602A439238
57	WDD2221602A439268
58	WDD2221602A439368
59	WDD2221621A438882
60	WDD2221622A434671
61	WDD2221622A435383
62	WDD2221622A435676
63	WDD2221622A435748
64	WDD2221622A436013
65	WDD2221622A436389
66	WDD2221622A438163
67	WDD2221622A438327
68	WDD2221622A438476
69	WDD2221622A438514
70	WDD2221622A438568
71	WDD2221622A438604
72	WDD2221622A438760
73	WDD2221622A438891
74	WDD2229802A434793
75	WDD2229802A435218
76	WDD2229832A434732
77	WDD2229832A434985
78	WDD2229832A434993
79	WDD2229832A436243
80	WDD2229832A436419
81	WDD2229832A436429
82	WDD2229832A436829

83	WDD2229832A437204
84	WDD2229832A437538
85	WDD2229832A437539
86	WDD2229832A438027
87	WDD2229832A438097
88	WDD2229832A438411
89	WDD2229832A438790
90	WDD2229832A438888
91	WDD2229832A438997
92	WDD2383421F073908
93	WDD2383422F073702
94	WDD2383422F073704
95	WDD2383422F073728
96	WDD2383422F073861
97	WDD2383422F073948
98	WDD2383422F073983
99	WDD2383422F074728
100	WDD2383422F074840
101	WDD2383422F074910
102	WDD2383422F075097
103	WDD2383422F075129
104	WDD2383422F075145
105	WDD2383422F075312
106	WDD2383422F077705
107	WDD2383482F074224
108	WDD2383482F074994
109	WDD2383482F075022
110	WDD2383482F075025
111	WDD2383482F075037
112	WDD2383482F075393
113	WDD2383482F078269
114	WDD2383482F078565
115	WDD2383482F079853
116	WDD2383482F080139
117	WDD2383482F080402
118	WDD2383482F080592
119	WDD2383612F076240
120	WDD2383612F076250
121	WDD2384422F073709
122	WDD2384422F073820

123	WDD2384422F073905
124	WDD2384422F077778
125	WDD2384422F080031
126	WDD2384422F080292
127	WDD2384422F080545
128	WDD2384482F073580
129	WDD2384482F074693
130	WDD2384482F074793
131	WDD2384482F075632
132	WDD2384482F075755
133	WDD2384482F075798
134	WDD2384612F075612
135	WDD2384612F075688