

Recall Detail

Ref No	10000855
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	LS350/LS500/LS500h/IS300h
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Run flat tire replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to an improper tire to wheel assembly process, there is a possibility that an abnormal noise and/or abnormal vibration may occur under certain driving conditions.
Remedial Action	Replace the tires
Build Dates	September 2017 ~ July 2018
Launch Date	March 2019
Tentative Date of Recall Completion	December 2020

1	JTHB4LFF005001399
2	JTHB4LFF005001953
3	JTHB4LFF005001967
4	JTHB4LFF005002312
5	JTHB4LFF105001489
6	JTHB4LFF105001511
7	JTHB4LFF105001671
8	JTHB4LFF305002479
9	JTHB4LFF305002577
10	JTHB4LFF405001924
11	JTHB4LFF505001446
12	JTHB4LFF505001740
13	JTHB4LFF505002337
14	JTHB4LFF505002614
15	JTHB4LFF505002645
16	JTHB4LFF605002573
17	JTHB4LFF705001058
18	JTHB4LFF705001156
19	JTHB4LFF805001599
20	JTHB4LFF805002364
21	JTHB4LFF805002428

22	JTHB4LFF905001725
23	JTHB4LFFX05001362
24	JTHB4LFFX05001586
25	JTHB5LFF005000556
26	JTHB5LFF005002999
27	JTHB5LFF005003148
28	JTHB5LFF005004901
29	JTHB5LFF005005000
30	JTHB5LFF105004292
31	JTHB5LFF205003183
32	JTHB5LFF205004401
33	JTHB5LFF205005189
34	JTHB5LFF305003080
35	JTHB5LFF305003158
36	JTHB5LFF305003788
37	JTHB5LFF305004326
38	JTHB5LFF405003959
39	JTHB5LFF405004321
40	JTHB5LFF505002383
41	JTHB5LFF505003744
42	JTHB5LFF505003906

43	JTHB5LFF605002487
44	JTHB5LFF605002554
45	JTHB5LFF605002781
46	JTHB5LFF605003882
47	JTHB5LFF605003932
48	JTHB5LFF605004336
49	JTHB5LFF605004837
50	JTHB5LFF705003972
51	JTHB5LFF705004393
52	JTHB5LFF705004474
53	JTHB5LFF905002466
54	JTHB5LFF905005352
55	JTHB5LFFX05002900
56	JTHB5LFFX05002976
57	JTHB5LFFX05003870
58	JTHB5LFFX05004436
59	JTHB5LFFX05004467
60	JTHBH1D2005069940
61	JTHBH1D2005070490
62	JTHBH1D2105069980
63	JTHBH1D2105072068
64	JTHBH1D2105073415
65	JTHBH1D2205067154
66	JTHBH1D2205070667
67	JTHBH1D2205070877
68	JTHBH1D2205071995
69	JTHBH1D2305066952
70	JTHBH1D2305067194
71	JTHBH1D2305070452
72	JTHBH1D2405067043
73	JTHBH1D2405069830
74	JTHBH1D2405070752
75	JTHBH1D2505072686
76	JTHBH1D2505073028
77	JTHBH1D2605066931
78	JTHBH1D2605070557
79	JTHBH1D2605070770
80	JTHBH1D2805069765
81	JTHBH1D2805070690
82	JTHBH1D2905070178
83	JTHBH1D2X05069797

84	JTHBH1D2X05070111
85	JTHBYLFF005000788
86	JTHBYLFF005001665
87	JTHBYLFF005002654
88	JTHBYLFF105002324
89	JTHBYLFF205002154
90	JTHBYLFF205003028
91	JTHBYLFF305000865
92	JTHBYLFF305003233
93	JTHBYLFF505001631
94	JTHBYLFF505002066
95	JTHBYLFF505002648
96	JTHBYLFF505003203
97	JTHBYLFF605000875
98	JTHBYLFF705002439
99	JTHBYLFF805000957
100	JTHBYLFF905000773
101	JTHBYLFF905000840
102	JTHBYLFF905001647
103	JTHBYLFF905002099
104	JTHBYLFF905002572
105	JTHBYLFFX05002600