

## Recall Detail

<b>Ref No</b>	<b>10000917</b>
<b>Manufacturer</b>	Toyota
<b>Vehicle Class</b>	LGV
<b>Model/Type</b>	Hiace (petrol)
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4988)
<b>Subject</b>	ECM Reprogram
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	In the automatic transmission of the subject vehicle, due to an improper programming of engine ECU to control oil pressure during changing gears, the oil pressure may become excessively high during changing gears. In this condition, if sudden acceleration is repeated, the clutch in the transmission may be damaged, resulting in poor acceleration. And in the worst case, the vehicle could lose motive power.
<b>Remedial Action</b>	Reprogram the ECM
<b>Build Dates</b>	January 2015 to October 2018
<b>Launch Date</b>	February 2020
<b>Tentative Date of Recall Completion</b>	December 2021

1	JTFHW02P000229619
2	JTFHW02P000244606
3	JTFHW02P000253063
4	JTFHW02P000268811
5	JTFHW02P000269442
6	JTFHW02P000270011
7	JTFHW02P000270168
8	JTFHW02P000270624
9	JTFHW02P000270686
10	JTFHW02P100229984
11	JTFHW02P100240421
12	JTFHW02P100245540
13	JTFHW02P100246221
14	JTFHW02P100269448
15	JTFHW02P100269627
16	JTFHW02P100270678
17	JTFHW02P200230321
18	JTFHW02P200240394
19	JTFHW02P200246468
20	JTFHW02P200246972
21	JTFHW02P200252691

22	JTFHW02P200253145
23	JTFHW02P200253260
24	JTFHW02P200269362
25	JTFHW02P200269376
26	JTFHW02P200269720
27	JTFHW02P200269765
28	JTFHW02P200270141
29	JTFHW02P200270382
30	JTFHW02P200270639
31	JTFHW02P300246009
32	JTFHW02P300268883
33	JTFHW02P300269290
34	JTFHW02P300269550
35	JTFHW02P300269774
36	JTFHW02P300270178
37	JTFHW02P300270259
38	JTFHW02P400214573
39	JTFHW02P400243877
40	JTFHW02P400244673
41	JTFHW02P400252367
42	JTFHW02P400252594

43	JTFHW02P400253907
44	JTFHW02P400269296
45	JTFHW02P400269489
46	JTFHW02P400269833
47	JTFHW02P400270075
48	JTFHW02P400270092
49	JTFHW02P400270464
50	JTFHW02P400270545
51	JTFHW02P400270562
52	JTFHW02P500228935
53	JTFHW02P500240468
54	JTFHW02P500244388
55	JTFHW02P500246707
56	JTFHW02P500247128
57	JTFHW02P500252541
58	JTFHW02P500253365
59	JTFHW02P500253589
60	JTFHW02P500269484
61	JTFHW02P500269727
62	JTFHW02P500270506
63	JTFHW02P600244822
64	JTFHW02P600252841
65	JTFHW02P600252953
66	JTFHW02P600269039
67	JTFHW02P700240357
68	JTFHW02P700240407
69	JTFHW02P700244456
70	JTFHW02P700269633
71	JTFHW02P700269986
72	JTFHW02P700270376
73	JTFHW02P800229304
74	JTFHW02P800240481
75	JTFHW02P800240559
76	JTFHW02P800244773
77	JTFHW02P800245339
78	JTFHW02P800252288
79	JTFHW02P800253456
80	JTFHW02P800253683
81	JTFHW02P800253750
82	JTFHW02P800269267
83	JTFHW02P900228596

84	JTFHW02P900240456
85	JTFHW02P900269908
86	JTFHW02P900270265
87	JTFHW02PX00240482
88	JTFHW02PX00243852
89	JTFHW02PX00244533
90	JTFHW02PX00245830
91	JTFHW02PX00268735
92	JTFHW02PX00268976
93	JTFHW02PX00269836
94	JTFHW02PX00270372
95	JTFHW02P300212331
96	JTFHW02P000261048
97	JTFHW02P000262006
98	JTFHW02P000262605
99	JTFHW02P000263950
100	JTFHW02P000267688
101	JTFHW02P100261494
102	JTFHW02P100261771
103	JTFHW02P100262533
104	JTFHW02P100262614
105	JTFHW02P100263133
106	JTFHW02P100263200
107	JTFHW02P100263648
108	JTFHW02P100265660
109	JTFHW02P100267618
110	JTFHW02P100267747
111	JTFHW02P200261830
112	JTFHW02P200262069
113	JTFHW02P200262198
114	JTFHW02P200262766
115	JTFHW02P200262816
116	JTFHW02P200263142
117	JTFHW02P200263528
118	JTFHW02P200265943
119	JTFHW02P300262260
120	JTFHW02P300262422
121	JTFHW02P300263022
122	JTFHW02P300263652
123	JTFHW02P300263926
124	JTFHW02P300263957

125	JTFHW02P300264770
126	JTFHW02P300265126
127	JTFHW02P300265370
128	JTFHW02P300265630
129	JTFHW02P300267345
130	JTFHW02P300267667
131	JTFHW02P400260971
132	JTFHW02P400261585
133	JTFHW02P400261666
134	JTFHW02P400261750
135	JTFHW02P400262266
136	JTFHW02P400262820
137	JTFHW02P400263336
138	JTFHW02P400263711
139	JTFHW02P400263756
140	JTFHW02P400263773
141	JTFHW02P400264020
142	JTFHW02P400267211
143	JTFHW02P400267581
144	JTFHW02P400267676
145	JTFHW02P400267693
146	JTFHW02P400267743
147	JTFHW02P500261918
148	JTFHW02P500263832
149	JTFHW02P500263846
150	JTFHW02P500264009
151	JTFHW02P500267024
152	JTFHW02P500267539
153	JTFHW02P600261149
154	JTFHW02P600262348
155	JTFHW02P600263208
156	JTFHW02P600263841
157	JTFHW02P600263998
158	JTFHW02P700261659
159	JTFHW02P700261922
160	JTFHW02P700262519
161	JTFHW02P700262925
162	JTFHW02P700263332
163	JTFHW02P700264187
164	JTFHW02P700264304
165	JTFHW02P700267347

166	JTFHW02P800261203
167	JTFHW02P800262724
168	JTFHW02P800262951
169	JTFHW02P800263050
170	JTFHW02P800263484
171	JTFHW02P800263565
172	JTFHW02P800265770
173	JTFHW02P800266062
174	JTFHW02P800267020
175	JTFHW02P800267549
176	JTFHW02P900260917
177	JTFHW02P900261419
178	JTFHW02P900261422
179	JTFHW02P900262330
180	JTFHW02P900262800
181	JTFHW02P900263476
182	JTFHW02P900263560
183	JTFHW02P900263641
184	JTFHW02P900265017
185	JTFHW02P900265518
186	JTFHW02P900265860
187	JTFHW02P900266863
188	JTFHW02P900267463
189	JTFHW02PX00261302
190	JTFHW02PX00261347
191	JTFHW02PX00261882
192	JTFHW02PX00261929
193	JTFHW02PX00262594
194	JTFHW02PX00263339
195	JTFHW02PX00264314
196	JTFHW02PX00265298
197	JTFHW02PX00265379
198	JTFHW02PX00265527
199	JTFHW02PX00267486
200	JTFHW02PX00267598