

Recall Detail

Ref No	10000956
Manufacturer	Bentley
Vehicle Class	Private car
Model/Type	Bentayga 4.0L V8 TFSI
Dealer (phone no)	Ap Lei Chau Service Center Tel: 25537713 Tsuen Wan Service Center Tel: 21119679 Kowloon Bay Service Center Tel: 22621288
Subject	Bentayga 4.0L V8 TFSI – Engine control module update check with fuel hose check
Progress	In process
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The fuel quick connect located in engine compartment on V8 petrol engine could be subjected to temperatures above the design operating specification limit. It is possible for the fuel quick connect material to soften at these elevated temperatures, which could potentially result in a fuel leak
Remedial Action	Engine control unit software update/ replace the fuel hose,
Build Dates	Model Year: From 2016 to 2018
Launch Date	20 Jul 2020
Tentative Date of Recall Completion	20 Jul 2021

SJAAB14V9LC029608
SJAAB14V8LC029356
SJAAB14V7LC028845
SJAAB14V4LC028303
SJAAB14V1LC029473
SJAAL34V9KC026733
SJAAL34V8KC024214
SJAAL14VXKC025420
SJAAL14VXKC023909
SJAAL14V9KC027496
SJAAL14V9KC024629
SJAAL14V8KC023309
SJAAL14V7KC026850
SJAAL14V7KC023883
SJAAL14V4KC025896

SJAAL14V2KC023970
SJAAL14V1KC023622
SJAAL14V0KC025233
SJAAL14V0KC024230
SJAAB34VXLC029340
SJAAB14V9LC029740
SJAAB14V4LC028317
SJAAB14V2LC028901
SJAAB14V1LC028159