

## Recall Detail

<b>Ref No</b>	<b>10000979</b>
<b>Manufacturer</b>	Nissan
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	SERENA E-POWER (C27)
<b>Dealer (phone no)</b>	Honest Motors Ltd. (Tel: 2216 8228)
<b>Subject</b>	Fog Lamp Inspection
<b>Progress</b>	Running
<b>Affected Vehicle Identification Number (VIN)</b>	List as below
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The Fog Lamp lens were came off by unexpected strong force during the part transportation from production plant.</p> <p>In some cases, the vehicle may not meet the regulation of optical axis of the fog lamp for each country.</p>
<b>Remedial Action</b>	<p>Fog Lamp Inspection.</p> <p>Replace Fog Lamp. (if necessary)</p>
<b>Build Dates</b>	2019
<b>Launch Date</b>	30/11/2020
<b>Tentative Date of Recall Completion</b>	30/11/2030

## SERENA E-POWER (C27)

<b>1</b>	HFC27-800101	<b>42</b>	HFC27-800142	<b>83</b>	HFC27-800183
<b>2</b>	HFC27-800102	<b>43</b>	HFC27-800143	<b>84</b>	HFC27-800184
<b>3</b>	HFC27-800103	<b>44</b>	HFC27-800144	<b>85</b>	HFC27-800185
<b>4</b>	HFC27-800104	<b>45</b>	HFC27-800145	<b>86</b>	HFC27-800186
<b>5</b>	HFC27-800105	<b>46</b>	HFC27-800146	<b>87</b>	HFC27-800187
<b>6</b>	HFC27-800106	<b>47</b>	HFC27-800147	<b>88</b>	HFC27-800188
<b>7</b>	HFC27-800107	<b>48</b>	HFC27-800148	<b>89</b>	HFC27-800189
<b>8</b>	HFC27-800108	<b>49</b>	HFC27-800149	<b>90</b>	HFC27-800190
<b>9</b>	HFC27-800109	<b>50</b>	HFC27-800150	<b>91</b>	HFC27-800191
<b>10</b>	HFC27-800110	<b>51</b>	HFC27-800151	<b>92</b>	HFC27-800192
<b>11</b>	HFC27-800111	<b>52</b>	HFC27-800152	<b>93</b>	HFC27-800193
<b>12</b>	HFC27-800112	<b>53</b>	HFC27-800153	<b>94</b>	HFC27-800194
<b>13</b>	HFC27-800113	<b>54</b>	HFC27-800154	<b>95</b>	HFC27-800195
<b>14</b>	HFC27-800114	<b>55</b>	HFC27-800155	<b>96</b>	HFC27-800196
<b>15</b>	HFC27-800115	<b>56</b>	HFC27-800156	<b>97</b>	HFC27-800197
<b>16</b>	HFC27-800116	<b>57</b>	HFC27-800157	<b>98</b>	HFC27-800198
<b>17</b>	HFC27-800117	<b>58</b>	HFC27-800158	<b>99</b>	HFC27-800199
<b>18</b>	HFC27-800118	<b>59</b>	HFC27-800159	<b>100</b>	HFC27-800200
<b>19</b>	HFC27-800119	<b>60</b>	HFC27-800160	<b>101</b>	HFC27-800201
<b>20</b>	HFC27-800120	<b>61</b>	HFC27-800161	<b>102</b>	HFC27-800202
<b>21</b>	HFC27-800121	<b>62</b>	HFC27-800162	<b>103</b>	HFC27-800203
<b>22</b>	HFC27-800122	<b>63</b>	HFC27-800163	<b>104</b>	HFC27-800204
<b>23</b>	HFC27-800123	<b>64</b>	HFC27-800164	<b>105</b>	HFC27-800205
<b>24</b>	HFC27-800124	<b>65</b>	HFC27-800165	<b>106</b>	HFC27-800206
<b>25</b>	HFC27-800125	<b>66</b>	HFC27-800166	<b>107</b>	HFC27-800207
<b>26</b>	HFC27-800126	<b>67</b>	HFC27-800167	<b>108</b>	HFC27-800208
<b>27</b>	HFC27-800127	<b>68</b>	HFC27-800168	<b>109</b>	HFC27-800209
<b>28</b>	HFC27-800128	<b>69</b>	HFC27-800169	<b>110</b>	HFC27-800210
<b>29</b>	HFC27-800129	<b>70</b>	HFC27-800170	<b>111</b>	HFC27-800211
<b>30</b>	HFC27-800130	<b>71</b>	HFC27-800171	<b>112</b>	HFC27-800212
<b>31</b>	HFC27-800131	<b>72</b>	HFC27-800172	<b>113</b>	HFC27-800213
<b>32</b>	HFC27-800132	<b>73</b>	HFC27-800173	<b>114</b>	HFC27-800214
<b>33</b>	HFC27-800133	<b>74</b>	HFC27-800174	<b>115</b>	HFC27-800215
<b>34</b>	HFC27-800134	<b>75</b>	HFC27-800175	<b>116</b>	HFC27-800216
<b>35</b>	HFC27-800135	<b>76</b>	HFC27-800176	<b>117</b>	HFC27-800217
<b>36</b>	HFC27-800136	<b>77</b>	HFC27-800177	<b>118</b>	HFC27-800218
<b>37</b>	HFC27-800137	<b>78</b>	HFC27-800178	<b>119</b>	HFC27-800219
<b>38</b>	HFC27-800138	<b>79</b>	HFC27-800179	<b>120</b>	HFC27-800220
<b>39</b>	HFC27-800139	<b>80</b>	HFC27-800180	<b>121</b>	HFC27-800221
<b>40</b>	HFC27-800140	<b>81</b>	HFC27-800181	<b>122</b>	HFC27-800222

<b>41</b>	HFC27-800141	<b>82</b>	HFC27-800182		
-----------	--------------	-----------	--------------	--	--