

Recall Detail

Ref No	10001048
Manufacturer	Mercedes-Benz AG
Vehicle Class	Light Goods Vehicle (Van)
Model/Type	Sprinter 907 with transmission 722.9
Dealer (phone no)	Fanling Commercial Vehicle Service Centre: 2637 2988 Lau Fau Shan Commercial Vehicle Service Centre: 2111 7428
Subject	Code the Electronic Stability Program control unit (2790609)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	We have determined in very rare cases that a temporary fault in the transmission-side park pawl function may occur in certain vehicles. If the driver has not applied the manual parking brake in such a rare case when parking the vehicle (contrary to the specification of the operator's manual), the vehicle may under certain circumstances roll away and the risk of an accident would exist. If the driver is still seated in the driver's seat when the vehicle starts to roll away, the vehicle can be brought to a standstill by directly actuating the service brake.
Remedial Action	As a precautionary measure, to perform the coding in Electronic Stability Program control unit on the affected vehicles.
Build Dates	02/07/2018 – 28/08/2019
Launch Date	24/01/2022
Tentative Date of Recall Completion	31/12/2022

1	WDB9071532N055021
2	WDB9071532N057009
3	WDB9071532N057011
4	WDB9071532N057241

5	WDB9071532N057532
6	WDB9071532N057533
7	WDB9071532N061559
8	WDB9071532N061563

9	WDB9071532N061564
10	WDB9071532N061568
11	WDB9071532N061804
12	WDB9071532N061805
13	WDB9071532N061806
14	WDB9071532N061811
15	WDB9076532P061841
16	WDB9071532N064584
17	W1V9071532N101706
18	WDB9076532P190406
19	WDB9076532P190738
20	W1V9076532P205420
21	W1V9076532P220711
22	W1V9076532P223134
23	W1V9076532P224133
24	W1V9076532P233962
25	WDB9071552N003251
26	WDB9071532N003261
27	WDB9076332P010353
28	WDB9076532P010605
29	WDB9076552P010756
30	WDB9072552N018075
31	WDB9076552P029211
32	WDB9076332P029644
33	WDB9076552P046738
34	WDB9076552P046739
35	WDB9076552P046740
36	WDB9071532N052203
37	WDB9071532N053541
38	WDB9071532N053778
39	WDB9071532N054276
40	WDB9071532N057010
41	WDB9071532N057012
42	WDB9071532N057013
43	WDB9071532N057014
44	WDB9071532N057015
45	WDB9071532N057016
46	WDB9071532N057017
47	WDB9071532N057018
48	WDB9071532N057019

49	WDB9071532N057020
50	WDB9071552N057074
51	WDB9071532N057242
52	WDB9071532N057243
53	WDB9071532N057244
54	WDB9071532N057245
55	WDB9071532N057246
56	WDB9071532N057247
57	WDB9071532N057527
58	WDB9071532N057528
59	WDB9071532N057529
60	WDB9071532N057530
61	WDB9071532N057531
62	WDB9071532N057534
63	WDB9071532N057535
64	WDB9071532N057536
65	WDB9071532N057537
66	WDB9076532P061158
67	WDB9076532P061159
68	WDB9076532P061160
69	WDB9071532N061560
70	WDB9071532N061561
71	WDB9071532N061562
72	WDB9071532N061565
73	WDB9071532N061566
74	WDB9071532N061567
75	WDB9071532N061569
76	WDB9071532N061802
77	WDB9071532N061803
78	WDB9071532N061807
79	WDB9071532N061808
80	WDB9071532N061809
81	WDB9071532N061810
82	WDB9071532N061812
83	WDB9076532P061842
84	WDB9071532N064366
85	WDB9071532N064585
86	WDB9071532N064586
87	WDB9071532N064587
88	WDB9071532N064588

89	WDB9071532N064589
90	WDB9071532N064590
91	WDB9071532N064813
92	WDB9071532N065214
93	WDB9071532N065215
94	WDB9071532N065613
95	WDB9071532N065817
96	WDB9071532N065818
97	WDB9071532N073265
98	WDB9076552P089619
99	WDB9076532P122443
100	WDB9076552P128243
101	WDB9076332P134772
102	WDB9076332P136880
103	WDB9076532P137760
104	WDB9076552P137783
105	WDB9076532P138293
106	WDB9076552P138311
107	WDB9076532P138681
108	WDB9076532P140050
109	WDB9076532P140528
110	WDB9076412P143397
111	WDB9076552P145012
112	WDB9076532P147413
113	WDB9076532P150676
114	WDB9076572P155507
115	WDB9076552P159931
116	WDB9076552P161744
117	WDB9076552P161745
118	WDB9076532P162680
119	WDB9076532P163120
120	WDB9076572P163571
121	WDB9076532P189712
122	WDB9076532P189713
123	WDB9076532P189714
124	WDB9076532P189715
125	WDB9076532P189716
126	WDB9076532P189717
127	WDB9076532P189718
128	WDB9076532P189719

129	WDB9076532P189720
130	WDB9076532P189721
131	WDB9076532P189722
132	WDB9076532P190404
133	WDB9076532P190405
134	WDB9076532P190407
135	WDB9076532P190732
136	WDB9076532P190733
137	WDB9076532P190734
138	WDB9076532P190735
139	WDB9076532P190736
140	WDB9076532P190737
141	WDB9076532P190739
142	WDB9076532P191089
143	WDB9076532P191090
144	WDB9076532P191091
145	WDB9076532P191092
146	WDB9076532P191093
147	W1V9076332P201164
148	W1V9076532P204915
149	W1V9076532P204916
150	W1V9076532P205694
151	W1V9076532P212864
152	W1V9076532P214594
153	W1V9076532P214744
154	W1V9076532P215277
155	W1V9076532P215278
156	W1V9076532P217679
157	W1V9076532P218158
158	W1V9076532P218799
159	W1V9076532P218961
160	W1V9076532P220710
161	W1V9076532P221467
162	W1V9076532P223459
163	W1V9076532P237501
164	W1V9076532P237506
165	W1V9076532P238165