

Recall Detail

Ref No	10001101
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	EQE/ 295
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	Connection of Structural Inlay to B-Pillar Trim (6891206)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8183) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	We have found that the connection of the B-pillar trim to the structural inlay in certain vehicles unfortunately might not meet specifications. In case of a crash with windowbag activation, the windowbag might not unfold as intended in the upper area of the B-pillar trim. Hereby, the B-pillar trim could also separate into the vehicle interior. Subsequently, the risk of injury for the vehicle occupants would be increased.
Remedial Action	As a precautionary measure, to check the B-pillar trim on the affected vehicles and replace it where necessary.
Build Dates	06/04/2022 – 11/07/2022
Launch Date	22/12/2022
Tentative Date of Recall Completion	31/12/2023

1

W1K2951212F002520

3

W1K2951212F002546

2

W1K2951212F002541

4

W1K2951212F002625

5	W1K2951212F002735	45	W1K2951212F004092
6	W1K2951212F002766	46	W1K2951212F004104
7	W1K2951212F002768	47	W1K2951212F004108
8	W1K2951212F002776	48	W1K2951212F004132
9	W1K2951212F002803	49	W1K2951212F004136
10	W1K2951212F002813	50	W1K2951212F004185
11	W1K2951212F002866	51	W1K2951212F004288
12	W1K2951212F002937	52	W1K2951212F004525
13	W1K2951212F002982	53	W1K2951212F004530
14	W1K2951212F002988	54	W1K2951212F004547
15	W1K2951212F003012	55	W1K2951212F004590
16	W1K2951212F003018	56	W1K2951212F004594
17	W1K2951212F003019	57	W1K2951212F004598
18	W1K2951212F003034	58	W1K2951212F004600
19	W1K2951212F003049	59	W1K2951212F004623
20	W1K2951212F003075	60	W1K2951212F004629
21	W1K2951212F003080	61	W1K2951212F004633
22	W1K2951212F003089	62	W1K2951212F004637
23	W1K2951212F003090	63	W1K2951212F004650
24	W1K2951212F003131	64	W1K2951212F004667
25	W1K2951212F003133	65	W1K2951212F004668
26	W1K2951212F003141	66	W1K2951212F004673
27	W1K2951212F003230	67	W1K2951212F004707
28	W1K2951212F003234	68	W1K2951212F004708
29	W1K2951212F003239	69	W1K2951212F004713
30	W1K2951212F003276	70	W1K2951212F004734
31	W1K2951212F003282	71	W1K2951212F004738
32	W1K2951212F003311	72	W1K2951212F004741
33	W1K2951212F003338	73	W1K2951212F004752
34	W1K2951212F003351	74	W1K2951212F004756
35	W1K2951212F003375	75	W1K2951212F004760
36	W1K2951212F003384	76	W1K2951212F004765
37	W1K2951212F003408	77	W1K2951212F004768
38	W1K2951212F003421	78	W1K2951212F004776
39	W1K2951212F003422	79	W1K2951212F004781
40	W1K2951212F003436	80	W1K2951212F004793
41	W1K2951212F003477	81	W1K2951212F004798
42	W1K2951212F003485	82	W1K2951212F004815
43	W1K2951212F003487	83	W1K2951212F004844
44	W1K2951212F003503	84	W1K2951212F004847

85	W1K2951212F004854	125	W1K2951212F005923
86	W1K2951212F004860	126	W1K2951212F005939
87	W1K2951212F004873	127	W1K2951212F005983
88	W1K2951212F004892	128	W1K2951212F005992
89	W1K2951212F004895	129	W1K2951212F005995
90	W1K2951212F004906	130	W1K2951212F006097
91	W1K2951212F004932	131	W1K2951212F006139
92	W1K2951212F004978	132	W1K2951212F006392
93	W1K2951212F004997	133	W1K2951212F006688
94	W1K2951212F005004	134	W1K2951212F006696
95	W1K2951212F005019	135	W1K2951212F006697
96	W1K2951212F005022	136	W1K2951212F006726
97	W1K2951212F005041	137	W1K2951212F006766
98	W1K2951212F005073	138	W1K2951212F006787
99	W1K2951212F005085	139	W1K2951212F006845
100	W1K2951212F005114	140	W1K2951212F006855
101	W1K2951212F005152	141	W1K2951212F006886
102	W1K2951212F005180	142	W1K2951212F006917
103	W1K2951212F005186	143	W1K2951212F006961
104	W1K2951212F005225	144	W1K2951212F006978
105	W1K2951212F005227	145	W1K2951212F006980
106	W1K2951212F005273	146	W1K2951212F007006
107	W1K2951212F005289	147	W1K2951212F007126
108	W1K2951212F005302	148	W1K2951212F007197
109	W1K2951212F005306	149	W1K2951212F007261
110	W1K2951212F005372	150	W1K2951212F007322
111	W1K2951212F005377	151	W1K2951212F007333
112	W1K2951212F005385	152	W1K2951212F007336
113	W1K2951212F005409	153	W1K2951212F007341
114	W1K2951212F005423	154	W1K2951212F007360
115	W1K2951212F005466	155	W1K2951212F007361
116	W1K2951212F005502	156	W1K2951212F007364
117	W1K2951212F005600	157	W1K2951212F007496
118	W1K2951212F005608		
119	W1K2951212F005628		
120	W1K2951212F005665		
121	W1K2951212F005802		
122	W1K2951212F005842		
123	W1K2951212F005848		
124	W1K2951212F005865		