

Recall Detail	
Ref No	10001108
Manufacturer	Suzuki Motor Corporation
Vehicle Class	Private Car
Model/Type	HUSTLER (AC1306) / SOLIO BANDIT (AUM412)
Dealer (phone no)	Island Motors Limited (Tel: 39138800)
Subject	Airbag Controller Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	There is a possibility of airbag will not deploy due to defective production of airbag controller.
Remedial Action	Airbag Controller Replacement
Build Dates	2022
Launch Date	02/02/2023
Tentative Date of Recall Completion	01/02/2024

1	MR52S310184
2	MR52S310185
3	MR52S310616
4	MR52S310703
5	MR52S310770
6	MA37S635984
7	MA37S635221
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	

21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	

41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	

80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	

