

## Recall Detail

<b>Ref No</b>	<b>10001128</b>
<b>Manufacturer</b>	Mercedes-Benz AG
<b>Vehicle Class</b>	Light Goods Vehicle (Van)
<b>Model/Type</b>	Sprinter/ 907
<b>Dealer (phone no)</b>	Fanling Commercial Vehicle Service Centre: 2637 2988 Lau Fau Shan Commercial Vehicle Service Centre: 2111 7428
<b>Subject</b>	Fuse rating for blower (8297010)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8183) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	We have determined in certain vehicles that the fuse layout of the interior blower unfortunately might not meet the requirements for permanent operation under the highest blower level. Influenced by certain premises, such as ambient and assembly space temperatures as well as usage, over time, this could lead to heat development in the area of the fuse mount. Consequently a risk of thermal damage during operation and a risk of injury cannot be ruled out.
<b>Remedial Action</b>	As a precautionary measure, to replace the fuse and its supply line and also relocate the fuse in the affected vehicles.
<b>Build Dates</b>	28/05/2018 – 02/12/2019
<b>Launch Date</b>	14/06/2023
<b>Tentative Date of Recall Completion</b>	31/03/2024

1

W1V9076332P201164

3

W1V9076532P191808

2

W1V9076532P191807

4

W1V9076532P203186

5	W1V9076532P204433	45	WDB9071532N061561
6	W1V9076532P204915	46	WDB9071532N061562
7	WDB9071532N003261	47	WDB9071532N061563
8	WDB9071532N052203	48	WDB9071532N061564
9	WDB9071532N053541	49	WDB9071532N061565
10	WDB9071532N053778	50	WDB9071532N061566
11	WDB9071532N054276	51	WDB9071532N061567
12	WDB9071532N055021	52	WDB9071532N061568
13	WDB9071532N057009	53	WDB9071532N061569
14	WDB9071532N057010	54	WDB9071532N061802
15	WDB9071532N057011	55	WDB9071532N061803
16	WDB9071532N057012	56	WDB9071532N061804
17	WDB9071532N057013	57	WDB9071532N061805
18	WDB9071532N057014	58	WDB9071532N061806
19	WDB9071532N057015	59	WDB9071532N061807
20	WDB9071532N057016	60	WDB9071532N061808
21	WDB9071532N057017	61	WDB9071532N061809
22	WDB9071532N057018	62	WDB9071532N061810
23	WDB9071532N057019	63	WDB9071532N061811
24	WDB9071532N057020	64	WDB9071532N061812
25	WDB9071532N057241	65	WDB9071532N064366
26	WDB9071532N057242	66	WDB9071532N064584
27	WDB9071532N057243	67	WDB9071532N064585
28	WDB9071532N057244	68	WDB9071532N064586
29	WDB9071532N057245	69	WDB9071532N064587
30	WDB9071532N057246	70	WDB9071532N064588
31	WDB9071532N057247	71	WDB9071532N064589
32	WDB9071532N057527	72	WDB9071532N064590
33	WDB9071532N057528	73	WDB9071532N064813
34	WDB9071532N057529	74	WDB9071532N065214
35	WDB9071532N057530	75	WDB9071532N065215
36	WDB9071532N057531	76	WDB9071532N065613
37	WDB9071532N057532	77	WDB9071532N065817
38	WDB9071532N057533	78	WDB9071532N065818
39	WDB9071532N057534	79	WDB9071532N073265
40	WDB9071532N057535	80	WDB9071552N003251
41	WDB9071532N057536	81	WDB9071552N057074
42	WDB9071532N057537	82	WDB9072552N018075
43	WDB9071532N061559	83	WDB9076332P010353
44	WDB9071532N061560	84	WDB9076332P029644

85	WDB9076332P134772	125	WDB9076532P189718
86	WDB9076332P136880	126	WDB9076532P189719
87	WDB9076332P167030	127	WDB9076532P189720
88	WDB9076412P134518	128	WDB9076532P189721
89	WDB9076412P134808	129	WDB9076532P189722
90	WDB9076412P134809	130	WDB9076532P190404
91	WDB9076412P136580	131	WDB9076532P190405
92	WDB9076412P137948	132	WDB9076532P190406
93	WDB9076412P138184	133	WDB9076532P190407
94	WDB9076412P138616	134	WDB9076532P190732
95	WDB9076412P143397	135	WDB9076532P190733
96	WDB9076412P143595	136	WDB9076532P190734
97	WDB9076412P144124	137	WDB9076532P190735
98	WDB9076412P144125	138	WDB9076532P190736
99	WDB9076412P144126	139	WDB9076532P190737
100	WDB9076412P144482	140	WDB9076532P190738
101	WDB9076532P003060	141	WDB9076532P190739
102	WDB9076532P010605	142	WDB9076532P191089
103	WDB9076532P061158	143	WDB9076532P191090
104	WDB9076532P061159	144	WDB9076532P191091
105	WDB9076532P061160	145	WDB9076532P191092
106	WDB9076532P061841	146	WDB9076532P191093
107	WDB9076532P061842	147	WDB9076552P010756
108	WDB9076532P122443	148	WDB9076552P029211
109	WDB9076532P137081	149	WDB9076552P046738
110	WDB9076532P137760	150	WDB9076552P046739
111	WDB9076532P138293	151	WDB9076552P046740
112	WDB9076532P138681	152	WDB9076552P089619
113	WDB9076532P140050	153	WDB9076552P128243
114	WDB9076532P140528	154	WDB9076552P137783
115	WDB9076532P147413	155	WDB9076552P138311
116	WDB9076532P150676	156	WDB9076552P145012
117	WDB9076532P162680	157	WDB9076552P159931
118	WDB9076532P163120	158	WDB9076552P161744
119	WDB9076532P189712	159	WDB9076552P161745
120	WDB9076532P189713	160	WDB9076572P155507
121	WDB9076532P189714	161	WDB9076572P163571
122	WDB9076532P189715		
123	WDB9076532P189716		
124	WDB9076532P189717		