

Recall Detail	
Ref No	10001129
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Corolla Cross (MXGA10)
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Reprogram the Skid Control ECU
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	This Recall is due to the Brake Actuator Assembly may falsely detect an overcurrent condition of the Electronic Parking Brake (EPB) Actuator and enter a failsafe mode, which illuminates the malfunction indicator lamp (MIL), displays a multi-information display (MID) message "Parking Brake Malfunction, Visit Your Dealer," and prevents the EPB from being engaged or disengaged. If the EPB cannot be engaged, the EPB MIL and MID warnings are ignored, and the vehicle is parked on a grade without being placed into "Park," the vehicle could rollaway, increasing the risk of a crash.
Remedial Action	Reprogram the Skid Control ECU
Build Dates	1 November 2021 to 19 April 2023
Launch Date	23 May 2023
Tentative Date of Recall Completion	31 Dec 2025

1	JTNAAAAB00J001078
2	JTNAAAAB00J001095
3	JTNAAAAB00J001131
4	JTNAAAAB00J001212
5	JTNAAAAB00J001307
6	JTNAAAAB10J001249
7	JTNAAAAB10J001266

8	JTNAAAAB10J001297
9	JTNAAAAB20J001082
10	JTNAAAAB30J001107
11	JTNAAAAB30J001317
12	JTNAAAAB40J000905
13	JTNAAAAB40J000953
14	JTNAAAAB40J001083

15	JTNAAAAB40J001147
16	JTNAAAAB40J001200
17	JTNAAAAB40J001245
18	JTNAAAAB40J001293
19	JTNAAAAB40J001309
20	JTNAAAAB50J000931
21	JTNAAAAB50J001111
22	JTNAAAAB50J001240
23	JTNAAAAB60J000887
24	JTNAAAAB60J000999
25	JTNAAAAB60J001165
26	JTNAAAAB60J001179
27	JTNAAAAB60J001201
28	JTNAAAAB60J001215
29	JTNAAAAB60J001294
30	JTNAAAAB70J000459
31	JTNAAAAB70J001109
32	JTNAAAAB70J001143
33	JTNAAAAB70J001188
34	JTNAAAAB80J001040

35	JTNAAAAB80J001099
36	JTNAAAAB80J001183
37	JTNAAAAB80J001328
38	JTNAAAAB90J000933
39	JTNAAAAB90J000995
40	JTNAAAAB90J001113
41	JTNAAAAB90J001211
42	JTNAAAAB90J001256
43	JTNAAAABX0J001122