

Recall Detail

Ref No	10001143
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	C-Class/ 206
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	Bolting of 12V and 48V Ground Connections (5491108 5491109 5491110)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8183) to clarify whether your vehicle is affected by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	We have determined that the bolts of specific ground connections on certain vehicles might be fastened with an insufficient torque. In this case, the wiring harness might not be fixed correctly. Subsequently, the electric resistance of the connection might increase. Thus, the temperature in this area might increase and a risk of thermal damage cannot be ruled out completely.
Remedial Action	As a precautionary measure, to check the bolting of the ground connections in the affected vehicles and correct this if necessary.
Build Dates	18/01/2022 – 15/03/2023
Launch Date	27/07/2023
Tentative Date of Recall Completion	30/09/2024

1

W1K2060422R009721

3

W1K2060422R010026

2

W1K2060422R009956

4

W1K2060422R010040

5	W1K2060422R010047	45	W1K2060422R017195
6	W1K2060422R010060	46	W1K2060422R030412
7	W1K2060422R010066	47	W1K2060422R030418
8	W1K2060422R010143	48	W1K2060422R030449
9	W1K2060422R010219	49	W1K2060422R030663
10	W1K2060422R010228	50	W1K2060422R030664
11	W1K2060422R010237	51	W1K2060422R030670
12	W1K2060422R010481	52	W1K2060422R030674
13	W1K2060422R010500	53	W1K2060422R030966
14	W1K2060422R010516	54	W1K2060422R030971
15	W1K2060422R010598	55	W1K2060422R048250
16	W1K2060422R010675	56	W1K2060422R048667
17	W1K2060422R010685	57	W1K2060422R048675
18	W1K2060422R010714	58	W1K2060422R049930
19	W1K2060422R010736	59	W1K2060422R054190
20	W1K2060422R010814	60	W1K2060422R055781
21	W1K2060422R010823	61	W1K2060422R064172
22	W1K2060422R010874	62	W1K2060422R064634
23	W1K2060422R010887	63	W1K2060422R064756
24	W1K2060422R011095	64	W1K2060422R070097
25	W1K2060422R011168	65	W1K2060422R071173
26	W1K2060422R011258	66	W1K2060422R071332
27	W1K2060422R011298	67	W1K2060422R071368
28	W1K2060422R011678	68	W1K2060422R091091
29	W1K2060422R011681	69	W1K2060422R091093
30	W1K2060422R011714	70	W1K2060422R114998
31	W1K2060422R011895	71	W1K2060422R115000
32	W1K2060422R012089	72	W1K2060422R115559
33	W1K2060422R012397	73	W1K2060422R124029
34	W1K2060422R013370	74	W1K2060422R124933
35	W1K2060422R013561		
36	W1K2060422R013814		
37	W1K2060422R014769		
38	W1K2060422R015083		
39	W1K2060422R015508		
40	W1K2060422R015535		
41	W1K2060422R016059		
42	W1K2060422R016209		
43	W1K2060422R016409		
44	W1K2060422R017055		