

Recall Detail

Ref No	10001178
Manufacturer	INFINITI
Vehicle Class	Private Car
Model/Type	M35H (Y51) & Q70L (GY51) & Q50S (V37)
Dealer (phone no)	Honest Motors Ltd. (Tel: 2216 8228)
Subject	Propeller Shaft Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	<p>Regarding V37 , Y51 and GY51 in Japan, North America, Europe, and GCC markets, which were produced by Tochigi plant, the supplier changed the ball yoke specification of the propeller shafts without reporting it to Nissan, which was different from the specification decided for mass production.</p> <p>As a result, there is a risk of non-conformity with durability specifications and a potential safety risk if the parts break while driving.</p>
Remedial Action	Replace Propeller Shaft.
Build Dates	2012-2018
Launch Date	15-Jul-2024
Tentative Date of Recall Completion	15-Jul-2029

Affected vehicles:**M35H (Y51)**

1	JN1BEAY51Z0440002	3	JN1BEAY51Z0440004	5	JN1BEAY51Z0440008
2	JN1BEAY51Z0440003	4	JN1BEAY51Z0440007	6	JN1BEAY51Z0440009

Q70L HYBRID (GY51)

1	JN1CEAY51Z0100001	26	JN1CEAY51Z0100027	51	JN1CEAY51Z0100052
2	JN1CEAY51Z0100002	27	JN1CEAY51Z0100028	52	JN1CEAY51Z0100053
3	JN1CEAY51Z0100003	28	JN1CEAY51Z0100029	53	JN1CEAY51Z0100054
4	JN1CEAY51Z0100005	29	JN1CEAY51Z0100030	54	JN1CEAY51Z0100055
5	JN1CEAY51Z0100006	30	JN1CEAY51Z0100031	55	JN1CEAY51Z0100056
6	JN1CEAY51Z0100007	31	JN1CEAY51Z0100032	56	JN1CEAY51Z0100057
7	JN1CEAY51Z0100008	32	JN1CEAY51Z0100033	57	JN1CEAY51Z0100058
8	JN1CEAY51Z0100009	33	JN1CEAY51Z0100034	58	JN1CEAY51Z0100059
9	JN1CEAY51Z0100010	34	JN1CEAY51Z0100035	59	JN1CEAY51Z0100060
10	JN1CEAY51Z0100011	35	JN1CEAY51Z0100036	60	JN1CEAY51Z0100061
11	JN1CEAY51Z0100012	36	JN1CEAY51Z0100037	61	JN1CEAY51Z0100062
12	JN1CEAY51Z0100013	37	JN1CEAY51Z0100038	62	JN1CEAY51Z0100063
13	JN1CEAY51Z0100014	38	JN1CEAY51Z0100039	63	JN1CEAY51Z0100064
14	JN1CEAY51Z0100015	39	JN1CEAY51Z0100040	64	JN1CEAY51Z0100065
15	JN1CEAY51Z0100016	40	JN1CEAY51Z0100041	65	JN1CEAY51Z0100066
16	JN1CEAY51Z0100017	41	JN1CEAY51Z0100042	66	JN1CEAY51Z0100067
17	JN1CEAY51Z0100018	42	JN1CEAY51Z0100043	67	JN1CEAY51Z0100068
18	JN1CEAY51Z0100019	43	JN1CEAY51Z0100044	68	JN1CEAY51Z0100069
19	JN1CEAY51Z0100020	44	JN1CEAY51Z0100045	69	JN1CEAY51Z0100070
20	JN1CEAY51Z0100021	45	JN1CEAY51Z0100046	70	JN1CEAY51Z0100071
21	JN1CEAY51Z0100022	46	JN1CEAY51Z0100047	71	JN1CEAY51Z0100072
22	JN1CEAY51Z0100023	47	JN1CEAY51Z0100048	72	JN1CEAY51Z0100073
23	JN1CEAY51Z0100024	48	JN1CEAY51Z0100049	73	JN1CEAY51Z0100074
24	JN1CEAY51Z0100025	49	JN1CEAY51Z0100050		
25	JN1CEAY51Z0100026	50	JN1CEAY51Z0100051		

Q50S HYBRID (V37)

1	JN1BAAV37Z0470004	10	JN1BAAV37Z0470014	19	JN1BAAV37Z0490002
2	JN1BAAV37Z0470005	11	JN1BAAV37Z0470071	20	JN1BAAV37Z0490003
3	JN1BAAV37Z0470006	12	JN1BAAV37Z0470073	21	JN1BAAV37Z0490004
4	JN1BAAV37Z0470007	13	JN1BAAV37Z0470076	22	JN1BAAV37Z0490005
5	JN1BAAV37Z0470008	14	JN1BAAV37Z0470080	23	JN1BAAV37Z0490006
6	JN1BAAV37Z0470009	15	JN1BAAV37Z0470081	24	JN1BAAV37Z0490007
7	JN1BAAV37Z0470010	16	JN1BAAV37Z0470082	25	JN1BAAV37Z0490008
8	JN1BAAV37Z0470011	17	JN1BAAV37Z0470084		
9	JN1BAAV37Z0470013	18	JN1BAAV37Z0490001		