	Recall Detail		
Ref No	10001186		
Manufacturer	Mercedes-Benz AG		
Vehicle Class	Passenger car		
Model/Type	S-Class/ 223 with M176 engine		
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171		
Subject	Lambda Control (5496234)		
Progress	Running		
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. (2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Customer Service hotline (Tel: 2504 6140) to clarify whether your vehicle is affected by this recall.		
Description of Defect, how it came to light, and possible consequences if ignored.	As part of this constant monitoring, we have found that the software of the engine control unit in certain vehicles unfortunately might not meet specifications. In this case, an increase of exhaust temperatures and a damage of surrounding components (e.g. engine wiring harness, catalytic converter) might occur. A loss of propulsion without prior warning and an increased risk of thermal damage cannot be ruled out.		
Remedial Action	As a precautionary measure, we will update the software of the engine control unit on the affected vehicles.		
Build Dates	12/07/2022 - 17/05/2023		
Launch Date	14/10/2024		
Tentative Date of Recall Completion	31/12/2025		

1	W1K2239762A169546	4	W1K2239762A172280
2	W1K2239762A169611	5	W1K2239762A175433
3	W1K2239762A169779	6	W1K2239762A175602

7	W1K2239762A175715	
3	W1K2239762A175798	
)	W1K2239762A175871	
.0	W1K2239762A182895	
.1	W1K2239762A188007	
.2	W1K2239762A194162	
.3	W1K2239762A219095	
.4	W1K2239762A220398	
.5	W1K2239762A223287	