

## Recall Detail

<b>Ref No</b>	<b>10001191</b>
<b>Manufacturer</b>	Mercedes-Benz AG
<b>Vehicle Class</b>	Passenger car
<b>Model/Type</b>	C-Class/ 206; CLE/ 236
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
<b>Subject</b>	Label Front Passenger Airbag Shutoff (5891750)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Customer Service hotline (Tel: 2504 6140) to clarify whether your vehicle is affected by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	As part of this constant monitoring, we have found that unfortunately the label regarding automatic front passenger airbag shutoff might not have been attached to the side wall of the instrument panel on certain vehicles. As a result, it might be mistakenly assumed, that a rearward-facing child seat on the front passenger seat would be detected automatically and thus, it might erroneously be installed. Since the front passenger airbag is permanently active on the affected vehicles, in this scenario, the risk of injury might increase in the event of a crash with airbag deployment.
<b>Remedial Action</b>	As a precautionary measure, we will check the label on the affected vehicles and attach it, if necessary.
<b>Build Dates</b>	28/10/2021 – 13/06/2024
<b>Launch Date</b>	10/12/2024
<b>Tentative Date of Recall Completion</b>	31/12/2025

2	W1K2062422F061672
3	W1K2062422F062403
4	W1K2062422F062914
5	W1K2062422F063020
6	W1K2062422F063438
7	W1K2062422F065630
8	W1K2062422F072360
9	W1K2062422F075060
10	W1K2062422F077474
11	W1K2062422F084943
12	W1K2363472F009073
13	W1K2363472F015558
14	W1K2363472F032105
15	W1K2363502F008988
16	W1K2363502F009059
17	W1K2363502F009084
18	W1K2363502F011209
19	W1K2363502F011256
20	W1K2363502F016349
21	W1K2363502F016471
22	W1K2363502F028631
23	W1K2363502F031066
24	W1K2363502F031186