

## Recall Detail

<b>Ref No</b>	<b>10001198</b>
<b>Manufacturer</b>	Kia
<b>Vehicle Class</b>	Commercial Vehicle
<b>Model/Type</b>	Sorento (MQ4)
<b>Dealer (phone no)</b>	2462 4621
<b>Subject</b>	DCT software update
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Transmission warning light comes on. Update software to improve gear shift logic.
<b>Remedial Action</b>	DCT software update
<b>Build Dates</b>	MY2021 - 2022
<b>Launch Date</b>	Jan 06, 2025
<b>Tentative Date of Recall Completion</b>	Jan 06, 2029

KNARH81BVM5069065
KNARH81BVM5069066
KNARH81BVM5069067
KNARH81BVM5069068
KNARH81BVM5069070
KNARH81BVM5069073
KNARH81BVM5069075
KNARH81BVM5069079
KNARH81BVM5069080
KNARH81BVM5069082
KNARH81BVM5069180
KNARH81BVM5069181
KNARH81BVM5098417
KNARH81BVM5098420
KNARH81BVM5098442
KNARH81BVM5098517
KNARH81BVM5098743
KNARH81BVM5098747
KNARH81BVM5098748
KNARH81BVM5098749
KNARH81BVM5098759

KNARH81BVM5098760
KNARH81BVM5098763
KNARH81BVM5098766
KNARH81BVM5098775
KNARH81BVM5098778
KNARH81BVM5098827
KNARH81BVM5098828
KNARH81BVM5098829
KNARH81BVM5098830
KNARH81BVM5098831
KNARH81BVM5098833
KNARH81BVM5098836
KNARH81BVM5099027
KNARH81BVN5126779
KNARH81BVN5126787
KNARH81BVN5126812
KNARH81BVN5126818
KNARH81BVN5126822
KNARH81BVN5126827
KNARH81BVN5126829
KNARH81BVN5150071

KNARH81BVN5150076
KNARH81BVN5150077
KNARH81BVN5150473
KNARH81BVN5161971
KNARH81BWM5068399
KNARH81BWM5068404
KNARH81BWM5068409
KNARH81BWN5126464
KNARH81BWN5135043
KNARH81BWN5135045
KNARH81BWN5135049
KNARH81BWN5135052
KNARH81BWN5135055
KNARH81BWN5135056
KNARH81BWN5135058
KNARH81BWN5135069
KNARH81BWN5135075