

Recall Detail

Ref No	10001204
Manufacturer	ASTON MARTIN
Vehicle Class	PRIVATE CAR
Model/Type	Valkyrie / Valkyrie spider
Dealer (phone no)	MF Jebsen Automotive Limited (3180 6608)
Subject	Replace the Rear Fuse Box Closing Panel Screws
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Incorrect screws were used to attach the rear fuse box closing panel in some vehicles. The incorrect screws may be able to clash with the wiring harness.
Remedial Action	The repair procedure involves the replacement of the screws for the rear fuse box closing panel and the replacement of any parts damaged by this defect.
Build Dates	Manufactured from June 2020 – Dec 2024
Launch Date	7 May 2025
Tentative Date of Recall Completion	October 2025

1	SCF4JRB4XNGS70078
2	SCF4JRB44NGS70108
3	SCF4JRB47NGS70118
4	SCF4KRB46PGS70126
5	SCF4JRC49RGS80038
6	SCF4JRC47RGS80054