

Recall Details	
Ref No.	10001205
Manufacturer	Jaguar
Vehicle Class	Private Car
Model/Type	E-PACE
Dealer (phone no. / e-mail)	British Motors Limited - (Tel: 2121 7100 or 2820 5150 / e-mail: info@jaguar.com.hk)
Subject	Passenger airbag replacement (H491)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	<p>During passenger airbag deployment, the airbag may tear as a result of the instrument panel airbag deployment door panel not being sufficiently weakened.</p> <p>A torn airbag may reduce the occupant protection, and therefore increase risk of injury in the event of a crash. A torn airbag may also allow the escape of hot gasses which may cause burns to occupants.</p>
Remedial Action	Replace passenger airbag
Build Dates	Model Year 2021-2023
Launch Date	1 June 2025
Tentative Date of Recall Completion	31 December 2030

1	SADFA2AX0M1022695
2	SADFA2AX1M1020616
3	SADFA2AX3M1022979
4	SADFA2AX4M1022988
5	SADFA2AXXM1016189
6	SADFB2AS7N1028058
7	SADFB2AS8M1016421