

Recall Detail	
Ref No	10001233
Manufacturer	ASTON MARTIN
Vehicle Class	PRIVATE CAR
Model/Type	DBX, DBX707 and DBX S
Dealer (phone no)	MF Jebsen Automotive Limited (3180 6608)
Subject	DBX Rear Lower Arm Bolt
Progress	Processing
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	<p>Aston Martin has determined that a defect which relates to motor vehicle safety may exist for certain DBX vehicles that were manufactured from 27 February 2020 and 5 November 2025.</p> <p>On affected vehicles, a reduced diameter shank bolt can cause the pin for the torque reaction link to move within the joint causing excessive wear and potential early failure.</p> <p>A failure of the rear lower suspension arm can affect vehicle handling or cause damage to other suspension components and the rear brakes. The failures can increase the risk of a crash.</p> <p>On the affected vehicles it is necessary to inspect the lower suspension arm for damage and to replace the bolts for the rear torque reaction links</p>
Remedial Action	All affected vehicles will have the rear torque reaction link bolts replaced with a larger diameter shank bolt and we will replace the lower suspension arms if necessary.
Build Dates	Feb 2020 to Nov 2025
Launch Date	20/4/2026
Tentative Date of Recall Completion	20/4/2027

#	VIN
1	SCFVTJAW5MTV00232
2	SCFVTJAW8MTV00323
3	SCFVTJAW8MTV00368
4	SCFVTJAW8MTV00385
5	SCFVTJAW3MTV00410
6	SCFVTJAW4MTV00481
7	SCFVTJAW1MTV00664
8	SCFVTJAW3MTV00665
9	SCFVTJAW6MTV01048
10	SCFVTJAW4MTV01100
11	SCFVTJAW7MTV02113
12	SCFVTJAW9MTV02114
13	SCFVTJAW6MTV02197
14	SCFVTJAW8MTV02198
15	SCFVTJAW3MTV02206
16	SCFVTJAW2MTV02245
17	SCFVTJAW1MTV02740
18	SCFVTJAW3MTV02755
19	SCFVTJAW2MTV03220
20	SCFVTJAW8MTV03271
21	SCFVTJAW3MTV03971
22	SD7VTJAWXNTV04082
23	SD7VTJAW3NTV04117
24	SD7VTJAW9NTV04297
25	SD7VTJAW2NTV05548
26	SD7VTJBW2PTV05891
27	SD7VUJBW0PTV06888
28	SD7VTJBW5PTV07019
29	SD7VTJBW4PTV07044
30	SD7VTJBW8PTV07113
31	SD7VTJAW1PTV07259
32	SD7VTJBW9PTV08240
33	SD7VTJBW5PTV09143
34	SD7VTJBW7PTV09144
35	SD7VTJBW0PTV09146
36	SD7VTJBW5RTV09307
37	SD7VTJBWXRTV09416
38	SD7VTJBW4RTV09427
39	SD7VTJBW1RTV10079
40	SD7VTJBW1RTV10373
41	SD7VTJBW3RTV10763
42	SD7VTJDW6STV11800
43	SD7VTJDW7STV11952

