

Recall Detail

| | |
|---|--|
| Ref No | 10000330 |
| Manufacturer | Lexus |
| Vehicle Class | Private Car |
| Model/Type | GS300 / RX300 |
| Dealer (phone no) | Crown Motors Limited (Tel: 2880 4922) |
| Subject | Brake master cylinder cup replacement |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | Insufficient lubricant polymers in the brake fluid, which may cause the brake master cylinder cup to become dry, resulting in a slight leakage of brake fluid. This in turn might activate the brake warning indicator on the meter cluster. |
| Remedial Action | Replace brake master cylinder cup |
| Build Dates | GS300: September 2004 ~ February 2006 RX300: February 2003 ~ February 2006 |
| Launch Date | 21 October 2010 |
| Tentative Date of Recall Completion | December 2018 |

| | |
|----|-------------------|
| 1 | JTJHF31U000002087 |
| 2 | JTJHF31U000010397 |
| 3 | JTJHF31U000010593 |
| 4 | JTJHF31U000011663 |
| 5 | JTJHF31U000016586 |
| 6 | JTJHF31U000023747 |
| 7 | JTJHF31U000025773 |
| 8 | JTJHF31U000031945 |
| 9 | JTJHF31U000033615 |
| 10 | JTJHF31U002002966 |
| 11 | JTJHF31U100001711 |
| 12 | JTJHF31U100005029 |
| 13 | JTJHF31U100007296 |
| 14 | JTJHF31U100011011 |
| 15 | JTJHF31U100012031 |
| 16 | JTJHF31U100022025 |
| 17 | JTJHF31U100022106 |
| 18 | JTJHF31U100024339 |
| 19 | JTJHF31U102002782 |
| 20 | JTJHF31U200002219 |
| 21 | JTJHF31U200008344 |

| | |
|----|-------------------|
| 22 | JTJHF31U200010434 |
| 23 | JTJHF31U200016766 |
| 24 | JTJHF31U200020770 |
| 25 | JTJHF31U200021711 |
| 26 | JTJHF31U200027766 |
| 27 | JTJHF31U300001984 |
| 28 | JTJHF31U300011348 |
| 29 | JTJHF31U300012337 |
| 30 | JTJHF31U300027260 |
| 31 | JTJHF31U302002718 |
| 32 | JTJHF31U302003903 |
| 33 | JTJHF31U302010933 |
| 34 | JTJHF31U302011323 |
| 35 | JTJHF31U400003324 |
| 36 | JTJHF31U400005008 |
| 37 | JTJHF31U400015540 |
| 38 | JTJHF31U400017529 |
| 39 | JTJHF31U400020687 |
| 40 | JTJHF31U400021077 |
| 41 | JTJHF31U400021953 |
| 42 | JTJHF31U400027929 |

| | |
|----|-------------------|
| 43 | JTJHF31U400028031 |
| 44 | JTJHF31U402006518 |
| 45 | JTJHF31U402006552 |
| 46 | JTJHF31U402007135 |
| 47 | JTJHF31U402007734 |
| 48 | JTJHF31U402008835 |
| 49 | JTJHF31U500002182 |
| 50 | JTJHF31U500007155 |
| 51 | JTJHF31U500008242 |
| 52 | JTJHF31U500009164 |
| 53 | JTJHF31U500010900 |
| 54 | JTJHF31U500016955 |
| 55 | JTJHF31U500018432 |
| 56 | JTJHF31U500020505 |
| 57 | JTJHF31U500024151 |
| 58 | JTJHF31U500024425 |
| 59 | JTJHF31U500027468 |
| 60 | JTJHF31U500028054 |
| 61 | JTJHF31U500031536 |
| 62 | JTJHF31U500032251 |
| 63 | JTJHF31U500033934 |
| 64 | JTJHF31U502010688 |
| 65 | JTJHF31U600001624 |
| 66 | JTJHF31U600001848 |
| 67 | JTJHF31U600004362 |
| 68 | JTJHF31U600018777 |
| 69 | JTJHF31U600027320 |
| 70 | JTJHF31U600032033 |
| 71 | JTJHF31U602002308 |
| 72 | JTJHF31U602002759 |
| 73 | JTJHF31U602004074 |
| 74 | JTJHF31U602007539 |
| 75 | JTJHF31U602010747 |
| 76 | JTJHF31U602014300 |
| 77 | JTJHF31U700001440 |
| 78 | JTJHF31U700004306 |
| 79 | JTJHF31U700006802 |
| 80 | JTJHF31U700009487 |
| 81 | JTJHF31U700010705 |
| 82 | JTJHF31U700014415 |
| 83 | JTJHF31U700018044 |
| 84 | JTJHF31U700021509 |
| 85 | JTJHF31U700027732 |

| | |
|-----|-------------------|
| 86 | JTJHF31U700028282 |
| 87 | JTJHF31U702008070 |
| 88 | JTJHF31U702010787 |
| 89 | JTJHF31U800001155 |
| 90 | JTJHF31U800001561 |
| 91 | JTJHF31U800006534 |
| 92 | JTJHF31U800007859 |
| 93 | JTJHF31U800009580 |
| 94 | JTJHF31U800009921 |
| 95 | JTJHF31U800010972 |
| 96 | JTJHF31U800011779 |
| 97 | JTJHF31U800012057 |
| 98 | JTJHF31U800020014 |
| 99 | JTJHF31U800023916 |
| 100 | JTJHF31U800026363 |
| 101 | JTJHF31U800027609 |
| 102 | JTJHF31U800033555 |
| 103 | JTJHF31U802000463 |
| 104 | JTJHF31U802004285 |
| 105 | JTJHF31U802007655 |
| 106 | JTJHF31U802007705 |
| 107 | JTJHF31U802008465 |
| 108 | JTJHF31U802013973 |
| 109 | JTJHF31U900001455 |
| 110 | JTJHF31U900001584 |
| 111 | JTJHF31U900001777 |
| 112 | JTJHF31U900002153 |
| 113 | JTJHF31U900007224 |
| 114 | JTJHF31U900007532 |
| 115 | JTJHF31U900009393 |
| 116 | JTJHF31U900010298 |
| 117 | JTJHF31U900011628 |
| 118 | JTJHF31U900015484 |
| 119 | JTJHF31U900018689 |
| 120 | JTJHF31U900022306 |
| 121 | JTJHF31U900026436 |
| 122 | JTJHF31U900034388 |
| 123 | JTJHF31U902004666 |
| 124 | JTJHF31U902005011 |
| 125 | JTJHF31U902006983 |
| 126 | JTJHF31UX00001321 |
| 127 | JTJHF31UX00012920 |
| 128 | JTJHF31UX00013324 |

| | |
|-----|-------------------|
| 129 | JTJHF31UX00016319 |
| 130 | JTJHF31UX00018894 |
| 131 | JTJHF31UX00026218 |
| 132 | JTJHF31UX00032391 |
| 133 | JTJHF31UX02004675 |
| 134 | JTJHF31UX02006779 |
| 135 | JTJHF31UX02007253 |
| 136 | JTJHF31U000015213 |
| 137 | JTJHF31U000028186 |
| 138 | JTJHF31U000028513 |
| 139 | JTJHF31U000028754 |
| 140 | JTJHF31U000029029 |
| 141 | JTJHF31U000030326 |
| 142 | JTJHF31U000034165 |
| 143 | JTJHF31U000034327 |
| 144 | JTJHF31U100015298 |
| 145 | JTJHF31U100016161 |
| 146 | JTJHF31U100023448 |
| 147 | JTJHF31U100027371 |
| 148 | JTJHF31U100028908 |
| 149 | JTJHF31U100030223 |
| 150 | JTJHF31U100034241 |
| 151 | JTJHF31U200029422 |
| 152 | JTJHF31U200029825 |
| 153 | JTJHF31U200031011 |
| 154 | JTJHF31U202004251 |
| 155 | JTJHF31U300015271 |
| 156 | JTJHF31U300016937 |
| 157 | JTJHF31U300028649 |
| 158 | JTJHF31U300033835 |
| 159 | JTJHF31U300034032 |
| 160 | JTJHF31U300034130 |
| 161 | JTJHF31U302005182 |
| 162 | JTJHF31U400016512 |
| 163 | JTJHF31U400016719 |
| 164 | JTJHF31U400016851 |
| 165 | JTJHF31U400021662 |
| 166 | JTJHF31U400027946 |
| 167 | JTJHF31U400028790 |
| 168 | JTJHF31U400033293 |
| 169 | JTJHF31U400034198 |
| 170 | JTJHF31U400034265 |
| 171 | JTJHF31U500017684 |

| | |
|-----|-------------------|
| 172 | JTJHF31U500023257 |
| 173 | JTJHF31U500028555 |
| 174 | JTJHF31U500028720 |
| 175 | JTJHF31U500029138 |
| 176 | JTJHF31U500029530 |
| 177 | JTJHF31U500034047 |
| 178 | JTJHF31U600014499 |
| 179 | JTJHF31U600015068 |
| 180 | JTJHF31U600016530 |
| 181 | JTJHF31U600016639 |
| 182 | JTJHF31U600025891 |
| 183 | JTJHF31U600028161 |
| 184 | JTJHF31U600029276 |
| 185 | JTJHF31U602003958 |
| 186 | JTJHF31U602004379 |
| 187 | JTJHF31U700007349 |
| 188 | JTJHF31U700015113 |
| 189 | JTJHF31U700016990 |
| 190 | JTJHF31U700021977 |
| 191 | JTJHF31U700029738 |
| 192 | JTJHF31U702004312 |
| 193 | JTJHF31U702004763 |
| 194 | JTJHF31U800007070 |
| 195 | JTJHF31U800028453 |
| 196 | JTJHF31U800029411 |
| 197 | JTJHF31U800029571 |
| 198 | JTJHF31U800030025 |
| 199 | JTJHF31U800031577 |
| 200 | JTJHF31U800034107 |
| 201 | JTJHF31U802000088 |
| 202 | JTJHF31U802014444 |
| 203 | JTJHF31U900017588 |
| 204 | JTJHF31U900027683 |
| 205 | JTJHF31U900028378 |
| 206 | JTJHF31U900029627 |
| 207 | JTJHF31U900029692 |
| 208 | JTJHF31UX00023139 |
| 209 | JTJHF31UX00023397 |
| 210 | JTJHF31UX00023819 |
| 211 | JTJHF31UX00025974 |
| 212 | JTJHF31UX00029359 |
| 213 | JTJHF31UX00029488 |
| 214 | JTJHF31UX00029779 |

| | |
|-----|-------------------|
| 215 | JTJHF31UX00029927 |
| 216 | JTJHF31UX00031211 |
| 217 | JTHBG96S005014063 |
| 218 | JTHBG96S005025189 |
| 219 | JTHBG96S105013729 |
| 220 | JTHBG96S105028022 |
| 221 | JTHBG96S205008104 |
| 222 | JTHBG96S205026540 |
| 223 | JTHBG96S305011092 |
| 224 | JTHBG96S305026708 |
| 225 | JTHBG96S405018181 |
| 226 | JTHBG96S405024854 |
| 227 | JTHBG96S405026071 |
| 228 | JTHBG96S405026295 |
| 229 | JTHBG96S505010154 |
| 230 | JTHBG96S505025303 |
| 231 | JTHBG96S505027763 |
| 232 | JTHBG96S505028847 |
| 233 | JTHBG96S605017453 |
| 234 | JTHBG96S605022474 |
| 235 | JTHBG96S705016229 |
| 236 | JTHBG96S705026856 |
| 237 | JTHBG96S805013288 |
| 238 | JTHBG96S805021312 |
| 239 | JTHBG96SX05011445 |
| 240 | JTHBG96SX05027497 |
| 241 | JTHBG96S005015701 |
| 242 | JTHBG96S205016073 |
| 243 | JTHBG96S305016275 |
| 244 | JTHBG96S405016172 |
| 245 | JTHBG96S505016567 |
| 246 | JTHBG96S605015489 |
| 247 | JTHBG96S705016117 |
| 248 | JTHBG96S705023150 |
| 249 | JTHBG96SX05013888 |