

Recall Detail	
Ref No	10000349
Manufacturer	Ford
Vehicle Class	N1 – Light Goods Vehicle
Model/Type	Transit
Dealer (phone no. / e-mail)	Future Motors Limited - (Tel: 28205151 / fordservice@futuremotors.com.hk)
Subject	Inspection of engine coolant hose
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	A potential touch condition between a cooling hose and fuel pipe could result in chafe damage to the coolant hose, resulting in coolant loss and overheating engine.
Remedial Action	Fit a double 'C' clip to reposition fuel lines to remove touch condition to coolant hose
Build Dates	2009 to 2010
Launch Date	20 June 2011
Tentative Date of Recall Completion	31 December 2019

1	WF0FXXTTFFAJ41536
2	WF0NXXTTFN9P86809
3	WF0XXXTTFXAL59894
4	WF0XXXTTFXAL59950