

Recall Detail

Ref No	10000370
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	ES300/RX300
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Crankshaft pulley inspection/replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Inadequate amount of adhesive agent applied between the outer ring and the torsional rubber damper (inner ring) in the crankshaft pulley, causing a possibility that the outer ring may become misaligned which can cause abnormal engine vibration. In some cases, the belt for the power steering pump may become detached from the pulley which could affect the power assist of the steering.
Remedial Action	Inspect or replace the crankshaft pulley
Build Dates	June 2004 ~ March 2005
Launch Date	9 November 2011
Tentative Date of Recall Completion	December 2018

1	JTHBF30G006029743
2	JTHBF30G006030651
3	JTHBF30G006030939
4	JTHBF30G006031573
5	JTHBF30G006032724
6	JTHBF30G006033940
7	JTHBF30G006034098
8	JTHBF30G006034392
9	JTHBF30G006034991
10	JTHBF30G006035865
11	JTHBF30G006036045
12	JTHBF30G006036434
13	JTHBF30G106029752
14	JTHBF30G106030125
15	JTHBF30G106031095
16	JTHBF30G106031386
17	JTHBF30G106031484
18	JTHBF30G106032926
19	JTHBF30G106033431
20	JTHBF30G106033655
21	JTHBF30G106034353
22	JTHBF30G106035535

23	JTHBF30G106035700
24	JTHBF30G106036071
25	JTHBF30G206032482
26	JTHBF30G206033048
27	JTHBF30G206033082
28	JTHBF30G206033132
29	JTHBF30G206033244
30	JTHBF30G206034698
31	JTHBF30G206034958
32	JTHBF30G206035110
33	JTHBF30G206035480
34	JTHBF30G306029607
35	JTHBF30G306029767
36	JTHBF30G306030322
37	JTHBF30G306031938
38	JTHBF30G306032278
39	JTHBF30G306032653
40	JTHBF30G306032989
41	JTHBF30G306035360
42	JTHBF30G306035438
43	JTHBF30G306036248
44	JTHBF30G406029678

45	JTHBF30G406029681
46	JTHBF30G406030152
47	JTHBF30G406030975
48	JTHBF30G406032015
49	JTHBF30G406032838
50	JTHBF30G406035271
51	JTHBF30G406035416
52	JTHBF30G406036100
53	JTHBF30G406036162
54	JTHBF30G506029656
55	JTHBF30G506030189
56	JTHBF30G506030466
57	JTHBF30G506030970
58	JTHBF30G506031651
59	JTHBF30G506031908
60	JTHBF30G506032833
61	JTHBF30G506033173
62	JTHBF30G506033822
63	JTHBF30G506034291
64	JTHBF30G506034436
65	JTHBF30G506035246
66	JTHBF30G606030198
67	JTHBF30G606030461
68	JTHBF30G606030993
69	JTHBF30G606031237
70	JTHBF30G606033988
71	JTHBF30G606034316
72	JTHBF30G606034414
73	JTHBF30G606034963
74	JTHBF30G606035465
75	JTHBF30G606035563
76	JTHBF30G606036776
77	JTHBF30G706030517
78	JTHBF30G706030985
79	JTHBF30G706031294
80	JTHBF30G706031361
81	JTHBF30G706031389
82	JTHBF30G706032719
83	JTHBF30G706033871
84	JTHBF30G706035751
85	JTHBF30G706036172
86	JTHBF30G806030784
87	JTHBF30G806031949

88	JTHBF30G806033104
89	JTHBF30G806033118
90	JTHBF30G806034267
91	JTHBF30G806035323
92	JTHBF30G806035449
93	JTHBF30G806036598
94	JTHBF30G806036889
95	JTHBF30G906030454
96	JTHBF30G906031099
97	JTHBF30G906032754
98	JTHBF30G906032799
99	JTHBF30G906033192
100	JTHBF30G906033211
101	JTHBF30G906034665
102	JTHBF30G906035332
103	JTHBF30G906035525
104	JTHBF30GX06029734
105	JTHBF30GX06031421
106	JTHBF30GX06031550
107	JTHBF30GX06031953
108	JTHBF30GX06033265
109	JTHBF30GX06036280
110	JTJHF31U000027443
111	JTJHF31U000031945
112	JTJHF31U0002002966
113	JTJHF31U100027290
114	JTJHF31U200029209
115	JTJHF31U200030490
116	JTJHF31U200031400
117	JTJHF31U200031624
118	JTJHF31U202002841
119	JTJHF31U300027260
120	JTJHF31U302002718
121	JTJHF31U302003903
122	JTJHF31U302003951
123	JTJHF31U400027929
124	JTJHF31U400031365
125	JTJHF31U402000217
126	JTJHF31U402000234
127	JTJHF31U402002534
128	JTJHF31U402004266
129	JTJHF31U402004879
130	JTJHF31U500027468

131	JTJHF31U500028054
132	JTJHF31U500031536
133	JTJHF31U500032251
134	JTJHF31U500033934
135	JTJHF31U502000050
136	JTJHF31U600027320
137	JTJHF31U600029875
138	JTJHF31U600030069
139	JTJHF31U600032033
140	JTJHF31U602002308
141	JTJHF31U602002759
142	JTJHF31U602006438
143	JTJHF31U700027424
144	JTJHF31U700027732
145	JTJHF31U700028282
146	JTJHF31U800027609
147	JTJHF31U800033555
148	JTJHF31U802004285
149	JTJHF31U900034388
150	JTJHF31U902004666
151	JTJHF31U902005011
152	JTJHF31UX00033430
153	JTJHF31UX02004675
154	JTJHF31U000028186
155	JTJHF31U000028513
156	JTJHF31U000028754
157	JTJHF31U000029029
158	JTJHF31U000030326
159	JTJHF31U000034165
160	JTJHF31U000034327
161	JTJHF31U100027371
162	JTJHF31U100028908
163	JTJHF31U100030223
164	JTJHF31U100034241
165	JTJHF31U200029422
166	JTJHF31U200029825
167	JTJHF31U200031011
168	JTJHF31U202004251
169	JTJHF31U300028649
170	JTJHF31U300033835
171	JTJHF31U300034032
172	JTJHF31U300034130
173	JTJHF31U302005182

174	JTJHF31U400027946
175	JTJHF31U400028790
176	JTJHF31U400033293
177	JTJHF31U400034198
178	JTJHF31U400034265
179	JTJHF31U500028555
180	JTJHF31U500028720
181	JTJHF31U500029138
182	JTJHF31U500029530
183	JTJHF31U500034047
184	JTJHF31U600028161
185	JTJHF31U600029276
186	JTJHF31U602003958
187	JTJHF31U602004379
188	JTJHF31U700029738
189	JTJHF31U702004312
190	JTJHF31U702004763
191	JTJHF31U800028453
192	JTJHF31U800029411
193	JTJHF31U800029571
194	JTJHF31U800030025
195	JTJHF31U800031577
196	JTJHF31U800034107
197	JTJHF31U802000088
198	JTJHF31U900027683
199	JTJHF31U900028378
200	JTJHF31U900029627
201	JTJHF31U900029692
202	JTJHF31UX00029359
203	JTJHF31UX00029488
204	JTJHF31UX00029779
205	JTJHF31UX00029927
206	JTJHF31UX00031211