

Recall Detail

Ref No	10000399
Manufacturer	Mitsubishi Fuso Truck & Bus Corporation
Vehicle Class	Truck
Model/Type	Fuso FEA, FEB, FEC, FGB, BE641
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Check fuel low pressure return hose for leaks
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	As part of our ongoing process and product quality monitoring, it was found that there would be a possibility that fuel return hose might come off at the connector (filter) and this causes fuel leakage.
Remedial Action	Add a hose clip to the fuel return hose for preventive measuring.
Build Dates	From 27/ 07/ 2011 to 12/ 06/ 2012
Launch Date	13/ 09/ 2012
Tentative Date of Recall Completion	31/ 12/ 2012

1	FGB71EA00001
2	FEA51BA00001
3	FEA51CA00001
4	FEB71EA00001
5	FEB91GA00001
6	FEC71EA00001
7	FEC71GA00001
8	FEC91GA00001
9	FEC91HA00001
10	FEC91KA00001
11	FEA21BA00002
12	FEB91GA00002
13	FEC71EA00002
14	FEC71GA00002
15	FEC91GA00002
16	FEC91HA00002
17	FEC91KA00002
18	FGB71EA00002
19	FEA51BA00002
20	FEA51CA00002

21	FEB91GA00003
22	FEC91GA00003
23	FEC91KA00003
24	FEB71EA00003
25	FEC71EA00003
26	FEC71GA00003
27	FEA21BA00003
28	FEA51BA00003
29	FEA51CA00003
30	FEC91KA00004
31	FEC91GA00004
32	FEC71GA00004
33	FEC71EA00004
34	FEB91GA00004
35	FEC91HA00004
36	FEA21BA00004
37	FEA51CA00004
38	FEA51BA00004
39	FEC91HA00005
40	FEC71GA00005

41	FEC91GA00005
42	FEC71EA00005
43	FEA21BA00005
44	FEA51BA00005
45	FEA51CA00005
46	FEC91KA00005
47	FEC71EA00006
48	FEC71GA00006
49	FEC91GA00006
50	FEC91HA00006
51	FEA21BA00006
52	FEA51BA00006
53	FEA51CA00006
54	FEC91KA00006
55	FEC71EA00007
56	FEC71GA00007
57	FEC91GA00007
58	FEC91HA00007
59	FEA21BA00007
60	FEA51BA00007
61	FEC71GA00008
62	FEC91GA00008
63	FEC91HA00008
64	FEC71EA00008
65	FEA21BA00008
66	FEA51BA00008
67	FEA51CA00008
68	FEC71GA00009
69	FEC91GA00009
70	FEC91HA00009
71	FEC71EA00009
72	FEA21BA00009
73	FEA51BA00009
74	FEA51CA00009
75	FEC71GA00010
76	FEC91GA00010
77	FEC91HA00010
78	FEC71EA00010
79	FEA51BA00010
80	FEC91GA00011

81	FEC71EA00011
82	FEC91HA00011
83	FEC71GA00011
84	FEA21BA00011
85	FEC91KA00011
86	FEA51BA00011
87	FEB91GA00011
88	FEC91GA00012
89	FEC91HA00012
90	FEC71GA00012
91	FEC91KA00012
92	FEA51BA00012
93	FEB71EA00012
94	FEC91GA00013
95	FEC91HA00013
96	FEC71EA00013
97	FEC71GA00013
98	FEC91GA00014
99	FEC91HA00014
100	FEC71EA00014
101	FEA51BA00014
102	FEC91GA00015
103	FEC91HA00015
104	FEC91GA00016
105	FEC91HA00016
106	FEC71EA00016
107	FEC71GA00016
108	FEC91KA00016
109	FEC91GA00017
110	FEC91HA00017
111	FEC91KA00017
112	FEC91GA00018
113	FEC91HA00018
114	FEC71GA00018
115	FEC91GA00019
116	FEC91KA00019
117	FEC91GA00020
118	FEC91HA00020
119	FEC91KA00020
120	FEC91GA00021

121	FEC71EA00021
122	FEC91GA00022
123	FEC71GA00022
124	FEC91GA00023
125	FEC71EA00023
126	FEC91GA00024
127	FEC91HA00024
128	FEC71GA00024
129	FEC91GA00025
130	FEC71GA00025
131	FEC91GA00028
132	FEC91HA00028
133	FEC91GA00030
134	FEC71GA00031
135	FEC71EA00032
136	FEC91GA00033
137	FEC91HA00033
138	FEC91HA00034
139	FEC71EA00034
140	FEC71EA00035
141	FEC71GA00035
142	FEC71GA00036
143	FEC71EA00037
144	FEC91HA00037
145	FEC71GA00038
146	FEC71GA00039
147	FEC91GA00040
148	FEC91HA00040
149	FEC71GA00042
150	FEC91GA00047
151	FEC91GA00049
152	FEC91GA00052
153	FEC91GA00056
154	FEC91GA00057
155	FEC91GA00059
156	FEC91GA00060
157	BE641JG10001
158	BE641GG10002
159	BE641JG10010
160	BE641JG10002

161	BE641GG10003
162	BE641GG10004
163	BE641JG10007
164	BE641GG10001