

Recall Detail

Ref No	10000462
Manufacturer	Mitsubishi Fuso Truck & Bus Corporation
Vehicle Class	Light Goods Vehicle & Bus
Model/Type	Fuso FE &BE
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	ATF hoses clamp replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to insufficient clamp force, the ATF hoses may be pulled out specially when ATF pressure becomes greater in cold weather. In the worst case, ATF hoses is pulled out, it causes a large ATF leakage and may suddenly lead to "vehicle not drivable".
Remedial Action	Replace the hose clamp with new one.
Build Dates	From 26/ 04/ 2012 to 03/ 09/ 2013
Launch Date	26/ 02/ 2014
Tentative Date of Recall Completion	31/ 12/ 2014

1	FEC71EA00057
2	FEC71GA00071
3	FEC71GA00072
4	FEC71EA00058
5	FEC71EA00059
6	FEC71GA00074
7	FEC71GA00075
8	FEB71EA10001
9	FEB71EA10003
10	FEB71EA10002
11	FEC71EA10001
12	FEC71EA10006
13	FEC71EA10004
14	FEC71EA10003
15	FEC71GA10001
16	FEC71GA10006
17	FEC71GA10004
18	FEC71GA10003
19	FEC91GA10001
20	FEC91HA10001

21	FEC91KA10003
22	FEC71EA10008
23	FEC91GA10004
24	FEC71EA10009
25	FEC71EA10011
26	FEC71GA10009
27	FEC71GA10010
28	FEC91HA10004
29	FEC91KA10005
30	FEB71EA10004
31	FEC71EA10013
32	FEC71GA10011
33	FEC91GA10006
34	FEC71EA10014
35	FEC71GA10014
36	FEC71EA10016
37	FEB71EA10005
38	FEC71GA10015
39	FEC91KA10002
40	FEC71EA10019

41	FEC71EA10020
42	FEC71GA10018
43	FEC71GA10019
44	FEB71EA10006
45	FEC71EA10022
46	FEC71EA10024
47	FEC71GA10021
48	FEC71GA10023
49	FEC71GA10024
50	FEC91GA10010
51	FEC91HA10007
52	FEC71EA10027
53	FEC71GA10026
54	FEC71GA10027
55	FEC91GA10011
56	FEC71EA10030
57	FEC91GA10015
58	FEC91HA10009
59	FEB74GA00011
60	FEB74GA00010
61	FEB74GA00012
62	FEB74GA00014
63	FEB74GA00013
64	FEA51BA10001
65	FEA51BA10002
66	FEB74GA00006
67	FEB74GA00009
68	FEB74GA00008
69	FEB74GA00007
70	BE641JH10017
71	BE641JH10028
72	BE641JH10027
73	BE641JH10026
74	BE641JH10025
75	BE641JH10024
76	BE641JH10023
77	BE641JH10022
78	BE641JH10021
79	BE641JH10020
80	BE641GH10004

81	BE641JH10019
82	BE641JH10018
83	BE641JH10001
84	BE641GH10002
85	BE641JH10030
86	BE641JH10016
87	BE641JH10015
88	BE641JH10014
89	BE641JH10012
90	BE641JH10011
91	BE641JH10010
92	BE641JH10009
93	BE641JH10008
94	BE641JH10006
95	BE641JH10005
96	BE641JH10004
97	BE641JH10003
98	BE641JH10002
99	BE641GH10003
100	BE641JH10047
101	BE641JH10063
102	BE641JH10062
103	BE641JH10061
104	BE641JH10059
105	BE641JH10058
106	BE641JH10057
107	BE641JH10056
108	BE641JH10055
109	BE641JH10054
110	BE641JH10053
111	BE641JH10052
112	BE641JH10051
113	BE641JH10050
114	BE641JH10031
115	BE641JH10039
116	BE641GH10007
117	BE641JH10032
118	BE641JH10034
119	BE641JH10035
120	BE641JH10036

121	BE641JH10046
122	BE641JH10038
123	BE641JH10049
124	BE641JH10042
125	BE641GH10005
126	BE641JH10044
127	BE641GH10006
128	BE641JH10045
129	BE641JH10033
130	BE641JH10037
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
150	
151	
152	
153	
154	
155	
156	
157	
158	
159	
160	

161	
162	
163	
164	
165	
166	
167	
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	
195	
196	
197	
198	
199	
200	