

## Recall Detail

<b>Ref No</b>	<b>10000474</b>
<b>Manufacturer</b>	Lamborghini
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Gallardo
<b>Dealer (phone no)</b>	29292919
<b>Subject</b>	Power Steering Update
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The persistent severe load conditions and mechanical stress, due to fluid pressure into the power steering system, a little hole might be developed in the pipe, which could result in a small fluid leakage
<b>Remedial Action</b>	Check the power steering system and replace it if out of standard.
<b>Build Dates</b>	Model Year 2004 – 2006 (VIN: LA00030 – LA03976)
<b>Launch Date</b>	April, 2014
<b>Tentative Date of Recall Completion</b>	December, 2014

1	ZHWGE11S94LA00938
2	ZHWGE11S94LA01250
3	ZHWGE11S54LA01441
4	ZHWGE11MX4LA01582
5	ZHWGE11S95LA02108
6	ZHWGE11S55LA02123
7	ZHWGE11S35LA02296
8	ZHWGE11S15LA02605
9	ZHWGE12T66LA03273
10	ZHWGE12T46LA03546
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	

21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	