

Recall Detail

Ref No	10000220
Manufacturer	Bentley
Vehicle Class	Private car
Model/Type	Arnage T, R & RL
Dealer (phone no)	Bentley Hong Kong (Tel:2553 7713)
Subject	Wheel bolts with dimensional errors
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	On the cars affected there is the potential for a wheel bolt to loosen in service. This defect could result in the affected wheel becoming detached from the hub.
Remedial Action	The wheel bolts with dimensional error is replaced by a dimensionally correct set of bolts to secure the road wheels to the hub.
Build Dates	
Launch Date	1 March 2007
Tentative Date of Recall Completion	30 April 2007

1	SCBLC37F96CH11225
2	SCBLC37F86CH11510
3	SCBLF34F26CH11529
4	SCBLE37G75CH19356
5	SCBLE37G26CH19427
6	SCBLE37G56CH19440
7	SCBLE37G75CH19311