

Recall Detail

Ref No	1000314
Manufacturer	Mitsubishi Motors Corporation
Vehicle Class	Passenger Car
Model/Type	Lancer CY4A
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Inspection of tyres
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	There are some tyres with scratch damage due to an equipment failure at the assembly process for tire and wheel. The damage on the tire may develop and, in the worse case scenario, could eventually result in loss of air pressure.
Remedial Action	Inspection of all tyres and replace it if damage.
Build Dates	Year 2009~2010
Launch Date	12 July 2010
Tentative Date of Recall Completion	31 December 2010

1	JMYSTCY4AAU001904
2	JMYSTCY4AAU002001
3	JMYSTCY4AAU002038
4	JMYSTCY4AAU002071
5	JMYSTCY4AAU002102
6	JMYSTCY4AAU002152
7	JMYSTCY4AAU002206
8	JMYSTCY4AAU002261
9	JMYSTCY4AAU002303
10	JMYSTCY4A9U002889
11	JMYSTCY4A9U002890
12	JMYSTCY4A9U002891
13	JMYSTCY4A9U002892
14	JMYSTCY4A9U002893
15	JMYSTCY4A9U002894
16	JMYSTCY4AAU002372
17	JMYSTCY4AAU002364
18	JMYSTCY4AAU002386
19	JMYSTCY4AAU002392
20	JMYSTCY4AAU002406

21	JMYSTCY4AAU002416
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	