

Recall Detail

Ref No	10000553
Manufacturer	Hino
Vehicle Class	Light Goods Vehicle & Medium Goods Vehicle
Model/Type	300 Series Hybrid LGV: XKU640R-HKUMS3, XKU710R-HKUQSQ3, XKU710R-HKUQS3, XKU720R-HKUQS3 MGV: XKU720R-HKUTS3, XKU730R-HKUTS3"
Dealer (phone no)	2820 5000
Subject	Replace Actuating Motors of Automatic Clutch Unit (ACU) of AMT Transmission on Hino 300 Hybrid (HV)
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	(1) Due to incorrect layout of electric wires, water sealing grommets may be deformed and cause water to enter the actuating motors in the Automatic Clutch Unit (ACU) of the AMT transmission. This may hinder the movement of the brushes. (2) Due to the inadequate programming of the control software, the actuator brushes may wear prematurely and cause the warning light to come on if the vehicle is started and stopped frequently. The clutch may become inoperable.
Remedial Action	To replace the ACU actuating motors and to reprogram the ECU control software of ACU in accordance with work procedure recommended by Hino Motors, Ltd.
Build Dates	Feb 2013 to Feb 2015
Launch Date	October 2015
Tentative Date of Recall Completion	December 2015

1	JHHBNS3F60K001001
2	JHHUNS1H10K001047
3	JHHUNS1H50K001049
4	JHHUNS1H10K001050
5	JHHUNS1H30K001051
6	JHHUNS1H50K001052
7	JHHUNS1H70K001053

8	JHHUNS3H40K001086
9	JHHUNS3H40K001119
10	JHHUNS3H10K001238
11	JHHUNS3H40K001248
12	JHHUNS3H20K001250
13	JHHYNS2H10K001064
14	JHHYNS3H60K001074

15	JHHYNS3H80K001075
16	JHHYNS3HX0K001076
17	JHHYNS2HX0K001077
18	JHHYNS2H10K001078
19	JHHYNS2H30K001079
20	JHHYNS2H10K001081
21	JHHYNS2H40K001088
22	JHHZNS2H40K001001
23	JHHZNS2H60K001002
24	JHHZNS2H80K001003
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	

55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	