

## **Documents required for application of Seating Capacity Adjustment for Private Cars**

- 1. Applicant shall complete the "Notice of Change of Personal Particulars or Vehicle Particulars" (Form TD559), and fill up the details for New Seating Capacity (excluding driver).
- 2. Scenarios and documents required for application of Seating Capacity Adjustment for Private Cars:

		<b>Documentary Proof</b>			roof	
Change	Descriptions	A	В	C	D	Remarks
Reduction	Removal of original seat(s), without change of seating arrangement of the remaining seat(s)			✓		Sealing of seat and seat belt anchorages are required
	Rearrangement of seating plan e.g. Removal of 3-seater bench seat and replaced by two individual seats	<b>√</b>	<b>√</b>	<b>√</b>		Proper functioning of the Supplemental Restraint System (SRS) should be endorsed by RVM (if any)
Addition	Restore the original seating arrangement by installation of the removed seats		<b>√</b>	<b>√</b>		Proper functioning of the Supplemental Restraint System (SRS) should be endorsed by RVM (if any)
	Rearrangement of seating plan by addition of extra seat(s) (Normally unacceptable)	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	Normally unacceptable; RPE Testing Report shall be produced if quality assurance is adequately proven and compliance with manufacturer's specifications

3. Documents required to support application:

A	Manufacturer's Supporting Document, including but not limited to, Declaration Letter, Body Builder Guide, Seat installation Manual, Service Manual, etc.
В	Evidence for O.E.M. Parts, such as Invoice, Parts Catalogue, Parts Manual with indication of O.E.M. Parts Numbers, etc.
С	Declaration Letter issued by Registered Vehicle Mechanics (RVM) on compliance of Manufacturer's recommended procedure and technical specifications.
D	Registered Professional Engineers (RPE) Testing Report on seat belt(s) and seat anchorages complying with Schedule 2 of Road Traffic (Safety Equipment) Regulations, Cap. 374F.

4. For inquiries, please feel free to contact Vehicle Safety Enforcement Section 2nd Unit at Tel.: (852) 3961 0308.