

安全召回詳情

編號	10000785
製造商	凌志
車輛類別	私家車
型號	GS450h/GS350/IS350
代理商 (查詢電話)	皇冠汽車有限公司(2880 4922)
主題	更換燃油脈動緩衝器
進度	進行中
受影響車輛的底盤號碼	見以下表列:
缺陷簡述及忽略的可能後果	是次召回之原因是與燃油脈動緩衝器內之隔膜有關，隔膜內的物料有可能在長時間使用後硬化，甚至出現裂痕，引致汽油滲漏。
修正行動	更換燃油脈動緩衝器
製造日期	GS450h: 2008 年 9 月至 2011 年 10 月 GS350: 2012 年 5 月至 2014 年 10 月 IS350: 2013 年 4 月至 2014 年 12 月
回收行動開始日期	2018 年 6 月
估計回收行動的完成日期	2019 年 12 月

1	JTHBC96S705017683
2	JTHBC96S005017685
3	JTHBC96S205017686
4	JTHBC96S405017687
5	JTHBC96S805017689
6	JTHBC96S405017690
7	JTHBC96S605017691
8	JTHBC96SX05017693
9	JTHBC96S105017694
10	JTHBC96S505017696
11	JTHBC96S005017699
12	JTHBC96S505017701
13	JTHBC96S005017704
14	JTHBC96S205017705
15	JTHBC96S405017706
16	JTHBC96S805017708
17	JTHBC96S605017710
18	JTHBC96S105017713
19	JTHBC96S505017715
20	JTHBC96S905017717
21	JTHBC96S205017719
22	JTHBC96S205017722
23	JTHBC96S605017724

24	JTHBC96SX05017726
25	JTHBC96S305017728
26	JTHBC96S105017730
27	JTHBC96S305017731
28	JTHBC96S505017732
29	JTHBC96S205017736
30	JTHBC96S405017737
31	JTHBC96S305017759
32	JTHBC96S705017781
33	JTHBC96S105017811
34	JTHBC96S005017847
35	JTHBC96S005017881
36	JTHBC96S705017943
37	JTHBC96S405017981
38	JTHBC96S505017990
39	JTHBC96S405018029
40	JTHBC96SX05018066
41	JTHBC96S605018095
42	JTHBC96S905018124
43	JTHBC96SX05018133
44	JTHBC96S705018140
45	JTHBC96S105018182
46	JTHBC96S405018192

47	JTHBC96S705018221
48	JTHBC96S305018250
49	JTHBC96S305018300
50	JTHBC96S505018329
51	JTHBC96S905018382
52	JTHBC96S405018581
53	JTHBC96S105018604
54	JTHBC96S905018611
55	JTHBC96S705018641
56	JTHBC96S505018685
57	JTHBC96S205018692
58	JTHBC96S505018718
59	JTHBC96S005018738
60	JTHBC96S305018765
61	JTHBC96S805018809
62	JTHBC96S205019292
63	JTHBC96SX05019671
64	JTHBC96S505019870
65	JTHBC96S905019905
66	JTHBC96S205019910
67	JTHBC96S905019922
68	JTHBC96S205019969
69	JTHBC96S605020090
70	JTHBC96S905020097
71	JTHBC96S605020106
72	JTHBC96S905020116
73	JTHBC96S105020272
74	JTHBC96S505020274
75	JTHBC96S705020275
76	JTHBC96S005020277
77	JTHBC96S405020279
78	JTHBC96S305020290
79	JTHBC96S105020305
80	JTHBC96S805020382
81	JTHBC96S405020606
82	JTHBC96S205020670
83	JTHBC96S705020678
84	JTHBC96S805020690
85	JTHBC96S005020702
86	JTHBC96SX05020707
87	JTHBC96S505020713

88	JTHBC96S905020729
89	JTHBC96S505020744
90	JTHBC96S205020765
91	JTHBC96SX05020786
92	JTHBC96S005020795
93	JTHBC96S205020801
94	JTHBC96S905020813
95	JTHBC96S905020844
96	JTHBC96S105020854
97	JTHBC96S505020985
98	JTHBC96S405020993
99	JTHBC96S505020999
100	JTHBC96S005021042
101	JTHBC96S605021059
102	JTHBC96S805021063
103	JTHBC96S905021072
104	JTHBC96SX05021081
105	JTHBC96S405021092
106	JTHBC96S705021099
107	JTHBC96S605021272
108	JTHBC96S905021329
109	JTHBC96SX05021436
110	JTHBC96S605021448
111	JTHBC96S805021466
112	JTHBC96S405021528
113	JTHBC96S305021567
114	JTHBC96S705021572
115	JTHBC96S305021651
116	JTHBC96S205021656
117	JTHBC96S505021683
118	JTHBC96S405021688
119	JTHBC96S405021741
120	JTHBC96SX05021789
121	JTHBC96S305021794
122	JTHBC96S505021800
123	JTHBC96S205021852
124	JTHBC96S705021877
125	JTHBC96S505021893
126	JTHBC96S605022017
127	JTHBC96S705022091
128	JTHBC96S605022096

129	JTHBC96S005022191
130	JTHBC96S505022204
131	JTHBC96S205022211
132	JTHBC96S605022230
133	JTHBC96S705022236
134	JTHBC96S505022252
135	JTHBC96S805022259
136	JTHBC96S705022270
137	JTHBC96S405022338
138	JTHBC96S305022346
139	JTHBC96S205022354
140	JTHBC96S805022360
141	JTHBC96S405022520
142	JTHBC96S105022524
143	JTHBC96S705022589
144	JTHBC96S005022594
145	JTHBC96S105022619
146	JTHBC96S705022625
147	JTHBC96S005022644
148	JTHBC96S705022656
149	JTHBC96S005022661
150	JTHBC96S105022667
151	JTHBC96S805022679
152	JTHBC96S805022696
153	JTHBC96S905022755
154	JTHBC96S405022758
155	JTHBC96S905022805
156	JTHBC96S005022854
157	JTHBC96S105022880
158	JTHBC96S905022898
159	JTHBC96S505022901
160	JTHBC96S305022928
161	JTHBC96S105022944
162	JTHBC96S405022985
163	JTHBC96S705022995
164	JTHBC96S405023005
165	JTHBC96S405023019
166	JTHBC96S605023037
167	JTHBC96SX05023302
168	JTHBC96S105023382
169	JTHBC96S805023766

170	JTHBC96S405023795
171	JTHBC96S305023805
172	JTHBC96S405024106
173	JTHBC96SX05024126
174	JTHBC96S605024172
175	JTHBC96S705024178
176	JTHBC96S405024185
177	JTHBC96S805024223
178	JTHBC96S205024248
179	JTHBC96SX05024305
180	JTHBC96S305024324
181	JTHBC96S205024332
182	JTHBC96S405024395
183	JTHBC96S005024460
184	JTHBC96S205024461
185	JTHBC96S805024464
186	JTHBC96S905024487
187	JTHBC96S405024493
188	JTHBC96S905024702
189	JTHBC96S205024721
190	JTHBC96S405024736
191	JTHBC96S205024752
192	JTHBC96S805024819
193	JTHBE5D2405000166
194	JTHBE5D2305000255
195	JTHBE5D2305001714
196	JTHBE5D2505002962
197	JTHBE5D2905003046
198	JTHBE5D2905003161
199	JTHBE5D2405003293
200	JTHBE5D2X05004559
201	JTHBE5D2105004577
202	JTHBE5D2X05004593
203	JTHBE5D2505005232
204	JTHBE5D2805005340
205	JTHBE5D2605005384
206	JTHBE5D2805005449
207	JTHBE5D2205005771
208	JTHBE5D2205008041
209	JTHBE5D2505008535
210	JTHBE5D2805008769

211	JTHBE5D2805009288
212	JTHBE5D2805010246
213	JTHBE5D2805010280
214	JTHBE5D2X05010295
215	JTHBE5D2605010746
216	JTHBE5D2505010771
217	JTHBE5D2205013742
218	JTHBE5D2205014549
219	JTHBE5D2205018231
220	JTHBE5D2605018829
221	JTHBE1BL105009198
222	JTHBE1BL905009272
223	JTHBE1BL505009303
224	JTHBE1BLX05009331
225	JTHBE1BL605009780
226	JTHBE1BL005010603
227	JTHBE5BL405010837
228	JTHBE5BLX05011006
229	JTHBE1BL705011702
230	JTHBE1BL505012413
231	JTHBE1BL905001866
232	JTHBE1BL205001904
233	JTHBE1BL505001928
234	JTHBE1BL405001953
235	JTHBE5BL005001973
236	JTHBE1BL205001997
237	JTHBE1BL205002017
238	JTHBE5BL605002027
239	JTHBE1BL405002052
240	JTHBE5BLX05002077
241	JTHBE5BL205002087
242	JTHBE1BL905002094
243	JTHBE1BL805002104
244	JTHBE1BL705002126
245	JTHBE5BL905002152
246	JTHBE5BL205002199
247	JTHBE1BL405002214
248	JTHBE5BL705002232
249	JTHBE1BL605002246
250	JTHBE1BL605002277
251	JTHBE1BL805002300

252	JTHBE1BL105002316
253	JTHBE1BL905002323
254	JTHBE1BL205002342
255	JTHBE1BL405002357
256	JTHBE5BL205002381
257	JTHBE1BL205002406
258	JTHBE5BL005002430
259	JTHBE1BL205002440
260	JTHBE1BL605002456
261	JTHBE1BLX05002475
262	JTHBE1BL005002503
263	JTHBE1BL005002520
264	JTHBE1BL805002541
265	JTHBE1BL005002548
266	JTHBE1BL005002579
267	JTHBE1BL605002618
268	JTHBE1BL905002628
269	JTHBE1BL605002635
270	JTHBE1BL105002686
271	JTHBE1BL905002709
272	JTHBE1BL905002760
273	JTHBE1BL105002784
274	JTHBE1BL605002814
275	JTHBE5BL905002832
276	JTHBE1BL705002871
277	JTHBE5BLX05002922
278	JTHBE1BLX05002959
279	JTHBE1BL705003230
280	JTHBE1BL705003759
281	JTHBE1BL205003815
282	JTHBE1BL105003840
283	JTHBE1BL105004910
284	JTHBE1BL605005082
285	JTHBE1BL805005164
286	JTHBE1BL405005940
287	JTHBE1BL905006193
288	JTHBE1BL405007087
289	JTHBE5BL905007125
290	JTHBE1BL905007151
291	JTHBE1BL105007189
292	JTHBE5BLX05007229

293	JTHBE1BL705007374
294	JTHBE1BL505008300
295	JTHBE1BL605008337
296	JTHBE1BL205008352
297	JTHBE1BL805008419
298	JTHBE5BL205008438
299	JTHBE5BLX05008557
300	JTHBE1BL605008645
301	JTHBE5BLX05008669
302	JTHBE5BL005008695
303	JTHBE1BL105008830
304	JTHBE1BL805008890
305	JTHBE5BL705008922
306	JTHBE1BL305009154
307	JTHBE1BL305012555
308	JTHBE1BL505012847
309	JTHBE1BL105012893
310	JTHBE1BL205013020
311	JTHBE5BLX05013192
312	JTHBE5BL705013232
313	JTHBE5BL505013312
314	JTHBE1BLX05014044
315	JTHBE1BL105014370
316	JTHBE1BL205019545
317	JTHBE1BL205019612
318	JTHBE1BL505019622
319	JTHBE5BLX05021812
320	JTHBE1BLX05021916
321	JTHBE1BL705021937
322	JTHBE5BL805022098
323	JTHBE1BL505024576
324	JTHBE1BL905024824
325	JTHBE1BLX05025965
326	JTHBE1BL605026742
327	JTHBE1BL605027731
328	JTHBE5BL405027945
329	JTHBE1BL805028931
330	JTHBE1BL805029061
331	JTHBE1BL305029257
332	JTHBE1BL805029304
333	JTHBE1BL805029397

334	JTHBE1BL605029821
335	JTHBE1BL505035416
336	JTHBE1BL205035566
337	JTHBE1BL805036740
338	JTHBE1BLX05038604
339	JTHBE1BL505044147
340	JTHBE1BL80A000215
341	JTHBE1BL60A001928