

安全召回詳情

編號	10000330
製造商	凌志
車輛類別	私家車
型號	GS300 / RX300
代理商 (查詢電話)	皇冠汽車有限公司(2880 4922)
主題	更換剎車總泵油封
進度	進行中
受影響車輛的底盤號碼	見以下表列:
缺陷簡述及忽略的可能後果	剎車液內作為潤滑劑的聚合物不足，令剎車總泵油封出現乾裂情況並滲出少許剎車液，導致儀錶板上的剎車燈亮著。
修正行動	更換剎車總泵油封
製造日期	GS300: 2004年9月 ~ 2006年2月 RX300: 2003年2月 ~ 2006年2月
回收行動開始日期	2010年10月21日
估計回收行動的完成日期	2018年12月

1	JTJHF31U000002087
2	JTJHF31U000010397
3	JTJHF31U000010593
4	JTJHF31U000011663
5	JTJHF31U000016586
6	JTJHF31U000023747
7	JTJHF31U000025773
8	JTJHF31U000031945
9	JTJHF31U000033615
10	JTJHF31U002002966
11	JTJHF31U100001711
12	JTJHF31U100005029
13	JTJHF31U100007296
14	JTJHF31U100011011
15	JTJHF31U100012031
16	JTJHF31U100022025
17	JTJHF31U100022106
18	JTJHF31U100024339
19	JTJHF31U102002782
20	JTJHF31U200002219
21	JTJHF31U200008344
22	JTJHF31U200010434
23	JTJHF31U200016766
24	JTJHF31U200020770
25	JTJHF31U200021711
26	JTJHF31U200027766

27	JTJHF31U300001984
28	JTJHF31U300011348
29	JTJHF31U300012337
30	JTJHF31U300027260
31	JTJHF31U302002718
32	JTJHF31U302003903
33	JTJHF31U302010933
34	JTJHF31U302011323
35	JTJHF31U400003324
36	JTJHF31U400005008
37	JTJHF31U400015540
38	JTJHF31U400017529
39	JTJHF31U400020687
40	JTJHF31U400021077
41	JTJHF31U400021953
42	JTJHF31U400027929
43	JTJHF31U400028031
44	JTJHF31U402006518
45	JTJHF31U402006552
46	JTJHF31U402007135
47	JTJHF31U402007734
48	JTJHF31U402008835
49	JTJHF31U500002182
50	JTJHF31U500007155
51	JTJHF31U500008242
52	JTJHF31U500009164

53	JTJHF31U500010900
54	JTJHF31U500016955
55	JTJHF31U500018432
56	JTJHF31U500020505
57	JTJHF31U500024151
58	JTJHF31U500024425
59	JTJHF31U500027468
60	JTJHF31U500028054
61	JTJHF31U500031536
62	JTJHF31U500032251
63	JTJHF31U500033934
64	JTJHF31U502010688
65	JTJHF31U600001624
66	JTJHF31U600001848
67	JTJHF31U600004362
68	JTJHF31U600018777
69	JTJHF31U600027320
70	JTJHF31U600032033
71	JTJHF31U602002308
72	JTJHF31U602002759
73	JTJHF31U602004074
74	JTJHF31U602007539
75	JTJHF31U602010747
76	JTJHF31U602014300
77	JTJHF31U700001440
78	JTJHF31U700004306
79	JTJHF31U700006802
80	JTJHF31U700009487
81	JTJHF31U700010705
82	JTJHF31U700014415
83	JTJHF31U700018044
84	JTJHF31U700021509
85	JTJHF31U700027732
86	JTJHF31U700028282
87	JTJHF31U702008070
88	JTJHF31U702010787
89	JTJHF31U800001155
90	JTJHF31U800001561
91	JTJHF31U800006534
92	JTJHF31U800007859
93	JTJHF31U800009580
94	JTJHF31U800009921
95	JTJHF31U800010972

96	JTJHF31U800011779
97	JTJHF31U800012057
98	JTJHF31U800020014
99	JTJHF31U800023916
100	JTJHF31U800026363
101	JTJHF31U800027609
102	JTJHF31U800033555
103	JTJHF31U802000463
104	JTJHF31U802004285
105	JTJHF31U802007655
106	JTJHF31U802007705
107	JTJHF31U802008465
108	JTJHF31U802013973
109	JTJHF31U900001455
110	JTJHF31U900001584
111	JTJHF31U900001777
112	JTJHF31U900002153
113	JTJHF31U900007224
114	JTJHF31U900007532
115	JTJHF31U900009393
116	JTJHF31U900010298
117	JTJHF31U900011628
118	JTJHF31U900015484
119	JTJHF31U900018689
120	JTJHF31U900022306
121	JTJHF31U900026436
122	JTJHF31U900034388
123	JTJHF31U902004666
124	JTJHF31U902005011
125	JTJHF31U902006983
126	JTJHF31UX00001321
127	JTJHF31UX00012920
128	JTJHF31UX00013324
129	JTJHF31UX00016319
130	JTJHF31UX00018894
131	JTJHF31UX00026218
132	JTJHF31UX00032391
133	JTJHF31UX02004675
134	JTJHF31UX02006779
135	JTJHF31UX02007253
136	JTJHF31U000015213
137	JTJHF31U000028186
138	JTJHF31U000028513

139	JTJHF31U000028754
140	JTJHF31U000029029
141	JTJHF31U000030326
142	JTJHF31U000034165
143	JTJHF31U000034327
144	JTJHF31U100015298
145	JTJHF31U100016161
146	JTJHF31U100023448
147	JTJHF31U100027371
148	JTJHF31U100028908
149	JTJHF31U100030223
150	JTJHF31U100034241
151	JTJHF31U200029422
152	JTJHF31U200029825
153	JTJHF31U200031011
154	JTJHF31U202004251
155	JTJHF31U300015271
156	JTJHF31U300016937
157	JTJHF31U300028649
158	JTJHF31U300033835
159	JTJHF31U300034032
160	JTJHF31U300034130
161	JTJHF31U302005182
162	JTJHF31U400016512
163	JTJHF31U400016719
164	JTJHF31U400016851
165	JTJHF31U400021662
166	JTJHF31U400027946
167	JTJHF31U400028790
168	JTJHF31U400033293
169	JTJHF31U400034198
170	JTJHF31U400034265
171	JTJHF31U500017684
172	JTJHF31U500023257
173	JTJHF31U500028555
174	JTJHF31U500028720
175	JTJHF31U500029138
176	JTJHF31U500029530
177	JTJHF31U500034047
178	JTJHF31U600014499
179	JTJHF31U600015068
180	JTJHF31U600016530
181	JTJHF31U600016639

182	JTJHF31U600025891
183	JTJHF31U600028161
184	JTJHF31U600029276
185	JTJHF31U602003958
186	JTJHF31U602004379
187	JTJHF31U700007349
188	JTJHF31U700015113
189	JTJHF31U700016990
190	JTJHF31U700021977
191	JTJHF31U700029738
192	JTJHF31U702004312
193	JTJHF31U702004763
194	JTJHF31U800007070
195	JTJHF31U800028453
196	JTJHF31U800029411
197	JTJHF31U800029571
198	JTJHF31U800030025
199	JTJHF31U800031577
200	JTJHF31U800034107
201	JTJHF31U802000088
202	JTJHF31U802014444
203	JTJHF31U900017588
204	JTJHF31U900027683
205	JTJHF31U900028378
206	JTJHF31U900029627
207	JTJHF31U900029692
208	JTJHF31UX00023139
209	JTJHF31UX00023397
210	JTJHF31UX00023819
211	JTJHF31UX00025974
212	JTJHF31UX00029359
213	JTJHF31UX00029488
214	JTJHF31UX00029779
215	JTJHF31UX00029927
216	JTJHF31UX00031211
217	JTHBG96S005014063
218	JTHBG96S005025189
219	JTHBG96S105013729
220	JTHBG96S105028022
221	JTHBG96S205008104
222	JTHBG96S205026540
223	JTHBG96S305011092
224	JTHBG96S305026708

225	JTHBG96S405018181
226	JTHBG96S405024854
227	JTHBG96S405026071
228	JTHBG96S405026295
229	JTHBG96S505010154
230	JTHBG96S505025303
231	JTHBG96S505027763
232	JTHBG96S505028847
233	JTHBG96S605017453
234	JTHBG96S605022474
235	JTHBG96S705016229
236	JTHBG96S705026856
237	JTHBG96S805013288
238	JTHBG96S805021312
239	JTHBG96SX05011445
240	JTHBG96SX05027497
241	JTHBG96S005015701
242	JTHBG96S205016073
243	JTHBG96S305016275
244	JTHBG96S405016172
245	JTHBG96S505016567
246	JTHBG96S605015489
247	JTHBG96S705016117
248	JTHBG96S705023150
249	JTHBG96SX05013888